

Ottumwa Regional Airport



Pavement Management Report

PREPARED BY

Applied Pavement Technology, Inc.
115 West Main Street, Suite 400
Urbana, Illinois 61801
(217) 398-3977
www.appliedpavement.com

JULY 2023



The preparation of this document was financed in part through an Airport Improvement Program grant from the Federal Aviation Administration (Project Number 3-19-0000-030-2022) as provided under Section 505 of the Airport and Airway Improvement Act of 1982, as amended. The contents do not necessarily reflect the DOT's official views or the policy of the FAA. Acceptance of this report by the FAA does not in any way constitute a commitment on the part of the United States to participate in any development depicted therein nor does it indicate the proposed development is environmentally acceptable in accordance with appropriate public laws.

OTTUMWA REGIONAL AIRPORT PAVEMENT MANAGEMENT REPORT

Prepared For:



Iowa Department of Transportation
Modal Transportation Bureau
800 Lincoln Way
Ames, Iowa 50010
515-239-1691
<https://iowadot.gov/aviation/>

Prepared By:



Applied Pavement Technology, Inc.
115 West Main Street, Suite 400
Urbana, Illinois 61801
217-398-3977
<https://www.appliedpavement.com>

In Association With:



Robinson Engineering Company
Consulting Engineers
819 Second Street NE
Independence, Iowa 50644
319-334-7211

TABLE OF CONTENTS

INTRODUCTION	1
PAVEMENT INVENTORY	3
PAVEMENT EVALUATION.....	6
Pavement Evaluation Procedure	6
Pavement Evaluation Results.....	7
Inspection Comments.....	14
Runways.....	14
Taxiways.....	14
Aprons.....	15
PAVEMENT MAINTENANCE AND REHABILITATION PROGRAM	16
Analysis Parameters.....	16
Critical PCIs.....	16
Localized Preventive Maintenance Policies and Unit Costs.....	16
Major Rehabilitation Unit Costs.....	16
Budget and Inflation Rate	16
Analysis Approach.....	16
Analysis Results.....	17
General Maintenance Recommendations	18
FAA Requirements (Public Law 103-305).....	18
FAA Advisory Circular 150/5830-7B, Appendix A. Pavement Management Program (PMP)	19
SUMMARY	27

LIST OF FIGURES

Figure 1. Pavement condition versus cost of repair.....	1
Figure 2. Pavement area by branch use at Ottumwa Regional Airport.	4
Figure 3. Ottumwa Regional Airport network definition map.	5
Figure 4. Visual representation of PCI scale on typical pavement surfaces.	6
Figure 5. PCI versus repair type.	7
Figure 6. Pavement area by PCI range at Ottumwa Regional Airport.....	8
Figure 7. Area-weighted PCI by branch use at Ottumwa Regional Airport.	9
Figure 8. Ottumwa Regional Airport PCI map.	10

LIST OF TABLES

Table 1. 2022 pavement evaluation results.....	11
Table 2. 5-year M&R program under an unlimited funding analysis scenario.	17
Table 3. Pavement inspection report.....	21

APPENDIXES

Appendix A. Cause of Distress Tables A-1
Appendix B. Inspection PhotographsB-1
Appendix C. Inspection Report.....C-1
Appendix D. Work History Report..... D-1
Appendix E. Localized Preventive Maintenance Policies and Unit Cost TablesE-1
Appendix F. Year 2023 Localized Preventive Maintenance Details F-1


INTRODUCTION

Applied Pavement Technology, Inc. (APTech), with assistance from Robinson Engineering Company Consulting Engineers (Robinson), updated the Airport Pavement Management System (APMS) for the Iowa Department of Transportation, Modal Transportation Bureau (Iowa DOT). The APMS provides a means to monitor the condition of the pavements within the state of Iowa and to proactively plan for their preservation.

As part of this project, pavement conditions at Ottumwa Regional Airport were assessed in November 2022 using the Pavement Condition Index (PCI) procedure. During a PCI inspection, the types, severities, and amounts of distress present in a pavement are quantified. This information is then used to develop a composite index that represents the overall condition of the pavement in numerical terms, ranging from 0 (failed) to 100 (excellent). The PCI provides an overall measure of condition and an indication of the level of work that will be required to maintain or repair a pavement. The distress information also provides insight into what is causing the pavement to deteriorate, which is the first step in selecting the appropriate repair action to correct the problem.

Programmed into an APMS, PCI information is used to determine when preventive maintenance actions (such as crack or joint sealing) are advisable and to identify the most cost-effective time to perform major rehabilitation (such as an overlay or whitetopping). Delaying maintenance and rehabilitation (M&R) until a pavement structure has seriously degraded can cost many times more than if M&R was applied earlier in a pavement's life cycle, as shown in Figure 1. From a safety perspective, pavement distresses, such as cracks and loose debris, may pose risks in terms of the potential for aircraft tire damage and the ability of a pilot to safely control aircraft.

Figure 1. Pavement condition versus cost of repair.



The pavement evaluation results for Ottumwa Regional Airport are presented within this report and can be used by Ottumwa Regional Airport, the Iowa DOT, and the Federal Aviation Administration (FAA) to identify, prioritize, and schedule pavement M&R actions at the airport. In addition to this report, the web-based interactive pavement data visualization tool IDEA, containing the information collected during this project, was updated and may be accessed from the [Iowa DOT's website](#) or directly ([Iowa APMS IDEA](#)).

PAVEMENT INVENTORY

The project began with a review of the existing inventory information pertaining to the pavements at Ottumwa Regional Airport. The date of original construction, along with the date of any subsequent rehabilitation; the location of completed work; and the type of work undertaken were gathered. The information was used to update the pavement management database and associated maps, as necessary, to account for pavement-related work that had been undertaken since the last time the airport was evaluated in 2019.

The pavement network at Ottumwa Regional Airport was then divided into branches, sections, and sample units. A branch is a single entity that serves a distinct function. For example, a runway is considered a branch because it serves a single function (allowing aircraft to take off and land). Taxiways and aprons are also separate branches.

Each branch was further divided into sections. Traditionally, sections are defined as parts of the branch that share common attributes, such as cross-section, date of last construction, traffic level, and performance. Using this approach, if a runway was built in 1968 and then extended in 1984, it would contain two separate sections.

To estimate the overall condition of a pavement section, each section was subdivided into sample units. Portions of these sample units were evaluated during the pavement inspection, and the collected information was extrapolated to predict the overall section condition and quantities of distress.

Approximately 1,953,700 square feet of pavement were evaluated at Ottumwa Regional Airport, as illustrated in Figure 2. This figure also shows the area-weighted age, in years, of the pavements at the time of the inspection. Figure 3 provides a map that details how the pavement network was divided into management units and identifies the sample units that were evaluated during the pavement inspection at Ottumwa Regional Airport.

Figure 2. Pavement area by branch use at Ottumwa Regional Airport.





FIGURE 3. NETWORK DEFINITION MAP.



NETWORK DEFINITION LEGEND

	BRANCH IDENTIFIER
	SECTION IDENTIFIER
	PCI VALUE
	SECTION BREAK LINE
	SAMPLE UNIT BREAK LINE
	SLAB JOINT
	SAMPLE UNIT NUMBER
	SAMPLE UNIT INSPECTED
	ADDITIONAL SAMPLE UNIT

applied pavement TECHNOLOGY
 115 W. Main Street, Suite 400
 Urbana, IL 61801
 Tel: 217-398-3977
 Fax: 217-398-4027

AGENCY: Iowa Department of Transportation
 Modal Transportation Bureau

LOCATION: Ottumwa Regional Airport
 Ottumwa, Iowa

PAGE TITLE: Network Definition Map

PROJECT DATE: OCT. 2022	CREATION DATE: OCT. 2022	PROJECT MANAGER: LJR	JOB NUMBER: 2021-125-AM01
DRAWING SCALE: 1"=300'	LAST MODIFIED DATE: MAY 2023	REVISED BY: DMS	DRAWN BY: KEW
FILENAME: Ottumwa.dwg	LAYOUT NAME/NUMBER: NET. DEF.	PAGE NUMBER: 5	

PAVEMENT EVALUATION


Pavement Evaluation Procedure

APTech inspected the pavements at Ottumwa Regional Airport using the PCI procedure described in:

- FAA Advisory Circular 150/5380-6C, [Guidelines and Procedures for Maintenance of Airport Pavements](#).
- FAA Advisory Circular 150/5380-7B, [Airport Pavement Management Program \(PMP\)](#).
- ASTM D5340-20, *Standard Test Method for Airport Pavement Condition Index Surveys*.

The PCI provides a numerical indication of overall pavement condition, as illustrated in Figure 4. The types and amounts of deterioration are used to calculate the PCI of the section. The PCI ranges from a value of 0, which represents a pavement in a failed condition, to a value of 100, which represents a pavement in excellent condition. It is important to note that factors other than overall PCI need to be considered when identifying the appropriate type of repair, including types of distress present and rate of deterioration. Also, since the PCI does not assess the structural integrity or capacity of the pavement structure, further testing may be needed to validate and refine the treatment strategy.

Figure 4. Visual representation of PCI scale on typical pavement surfaces.



Note: Photographs shown are not specific to Ottumwa Regional Airport.

Generally, pavements with relatively high PCIs that are not exhibiting significant load-related distress will benefit from preventive maintenance actions, such as crack sealing or joint resealing. As the PCI drops, the pavements may require major rehabilitation, such as an overlay or whitetopping. In some situations where the PCI has dropped low enough, reconstruction may be the only viable alternative due to the substantial damage to the pavement structure. Figure 5 illustrates how the appropriate repair type varies with the PCI of a pavement section and provides the corresponding colors used for the maps and charts in this report for each range of PCIs.

Figure 5. PCI versus repair type.

PCI Range	Repair
86-100	Preventive Maintenance
71-85	
56-70	
41-55	Major Rehabilitation
26-40	Reconstruction
11-25	
0-10	

The types of distress identified during the PCI inspection provide insight into the cause of pavement deterioration, which is useful when selecting M&R strategies. Understanding the cause of distress helps in selecting a rehabilitation alternative that corrects the cause and thus eliminates or delays its recurrence. PCI distress types are characterized as:

- Load-related—These distress types are defined as being caused by aircraft or vehicular traffic and may indicate a structural deficiency. Examples of load-related distress include alligator cracking on asphalt-surfaced pavements and corner breaks on portland cement concrete (PCC) pavements.
- Climate/durability-related—These distress types often signify the presence of aged or environmentally susceptible (or both) material and include durability-related issues. Examples of climate/durability-related distress include weathering on asphalt-surfaced pavements, which is climate-related, and durability cracking on PCC pavements, which is durability-related.
- Other—Distress types that fall into this category cannot be attributed solely to load or climate/durability. Examples of this type of distress include depressions on asphalt-surfaced pavements and shrinkage cracking on PCC pavements.

Appendix A identifies the distress types considered during a PCI inspection and describes the likely cause of each distress type. It should be noted that a PCI is based on visual signs of pavement deterioration and does not provide a measure of structural capacity.

Pavement Evaluation Results

The pavements at Ottumwa Regional Airport were inspected in November 2022. The 2022 area-weighted condition of Ottumwa Regional Airport is 82, with conditions ranging from 26 to 100 (on a scale of 0 [failed] to 100 [excellent]). During the previous pavement inspection in 2019, the area-weighted PCI of the airport was 91.

Figure 6 summarizes the overall condition of the pavements at Ottumwa Regional Airport, and Figure 7 presents area-weighted condition (average PCI adjusted to account for the relative size of the pavement sections) by branch use. Figure 8 is a map that displays the condition of the evaluated pavements. Table 1 summarizes the results of the pavement evaluation. Appendix B presents photographs taken during the PCI inspection, and Appendix C contains detailed information on the distress types observed during the visual survey. Appendix D includes detailed work history information that was collected during the record review process.

Figure 6. Pavement area by PCI range at Ottumwa Regional Airport.




Figure 7. Area-weighted PCI by branch use at Ottumwa Regional Airport.
(Values on chart are area-weighted)





FIGURE 8. PCI MAP.



LEGEND	
	BRANCH IDENTIFIER
	SECTION IDENTIFIER
	PCI VALUE
	SECTION BREAK LINE

PAVEMENT CONDITION INDEX	
PCI	
86-100	Green
71-85	Light Green
56-70	Yellow-Green
41-55	Yellow
26-40	Orange
11-25	Red-Orange
0-10	Red

applied pavement
TECHNOLOGY

115 W. Main Street, Suite 400
Urbana, IL 61801
Tel: 217-398-3977
Fax: 217-398-4027

Robinson Engineering Company
Consulting Engineers

819 Second Street NE
Independence, Iowa 50644
319-334-7211

AGENCY: **Iowa Department of Transportation**
Modal Transportation Bureau

LOCATION: **Ottumwa Regional Airport**
Ottumwa, Iowa

PAGE TITLE: **2022 Pavement Condition Index Map**

PROJECT DATE: OCT. 2022	CREATION DATE: OCT. 2022	PROJECT MANAGER: LJR	JOB NUMBER: 2021-125-AM01
DRAWING SCALE: 1"=300'	LAST MODIFIED DATE: MAY 2023	REVISED BY: DMS	DRAWN BY: KEW
FILENAME: Ottumwa.dwg	LAYOUT NAME/NUMBER: PCI	PAGE NUMBER: 10	

Table 1. 2022 pavement evaluation results.

Branch	Section	Surface Type	Section Area (sf)	LCD	2022 PCI	% Distress Due to Load	% Distress Due to Climate/Durability	% Distress Due to Other	Type of Distress
A01OT	01	AAC	20,450	6/1/2007	33	37	51	12	Alligator Cracking, Block Cracking, Patching, Shoving, Swelling, Weathering
A01OT	02	APC	35,525	6/30/1970	29	11	86	3	Alligator Cracking, Block Cracking, Depression, Joint Reflection Cracking, Swelling, Weathering
A01OT	03	PCC	38,700	4/3/2021	98	0	71	29	Joint Spalling, Joint Seal Damage
A01OT	04	APC	12,713	6/1/2007	32	21	63	16	Alligator Cracking, Block Cracking, Depression, Joint Reflection Cracking, L&T Cracking, Swelling, Weathering
A01OT	05	APC	9,713	1/1/1970	26	28	72	0	Alligator Cracking, Block Cracking, Joint Reflection Cracking, Weathering
A01OT	06	PCC	36,044	8/3/2018	93	13	81	6	Blowup, Corner Spalling, Joint Seal Damage, LTD Cracking
A01OT	07	PCC	34,176	8/3/2019	100	0	0	100	Joint Spalling
A01OT	08	PCC	25,031	8/3/2016	95	15	72	13	Corner Break, Corner Spalling, Joint Spalling, Joint Seal Damage
A01OT	09	PCC	12,163	4/3/2022	100	0	0	0	No distress
A02OT	01	APC	71,191	6/30/1970	28	25	75	0	Alligator Cracking, Block Cracking, Joint Reflection Cracking, Weathering
A02OT	02	AC	79,574	8/11/2001	51	44	52	4	Alligator Cracking, Depression, L&T Cracking, Raveling, Rutting, Weathering
A02OT	03	APC	5,600	2/11/1970	27	41	59	0	Alligator Cracking, L&T Cracking, Patching, Weathering
A02OT	04	APC	3,150	2/11/2012	55	36	64	0	Alligator Cracking, L&T Cracking, Weathering
R04OT	01	APC	37,912	8/1/2009	95	0	100	0	Joint Reflection Cracking

Table 1. 2022 pavement evaluation results (continued).

Branch	Section	Surface Type	Section Area (sf)	LCD	2022 PCI	% Distress Due to Load	% Distress Due to Climate/Durability	% Distress Due to Other	Type of Distress
R04OT	02	APC	322,356	8/1/2009	95	0	100	0	Joint Reflection Cracking
R04OT	03	AC	49,829	8/4/2009	100	0	0	0	No distress
R04OT	04	PCC	40,000	6/3/2018	97	0	52	48	ASR, Joint Seal Damage
R13OT	01	PCC	601,045	6/3/2018	96	23	42	35	Joint Spalling, Joint Seal Damage, LTD Cracking, Shrinkage Cracking
TAOT	01	AC	59,790	6/1/2004	73	0	100	0	L&T Cracking, Raveling, Weathering
TAOT	02	AC	6,507	5/1/2004	39	37	63	0	Alligator Cracking, L&T Cracking, Patching, Weathering
TAOT	03	AC	68,546	8/4/2002	57	51	48	1	Alligator Cracking, Depression, L&T Cracking, Rutting, Weathering
TAOT	04	AAC	7,434	8/1/2009	54	12	88	0	Alligator Cracking, L&T Cracking, Raveling, Weathering
TAOT	05	AAC	8,374	8/1/2009	83	31	61	8	Alligator Cracking, L&T Cracking, Patching, Swelling, Weathering
TAOT	06	APC	83,942	6/30/1970	30	26	65	9	Alligator Cracking, Block Cracking, Joint Reflection Cracking, L&T Cracking, Swelling, Weathering
TAOT	07	PCC	28,447	6/3/2018	98	0	100	0	Joint Seal Damage
TAOT	08	PCC	42,805	6/3/2018	97	0	73	27	Joint Spalling, Joint Seal Damage, Shrinkage Cracking
TBOT	01	APC	23,338	6/1/2006	26	21	79	0	Alligator Cracking, Block Cracking, Joint Reflection Cracking, L&T Cracking, Weathering
TBOT	02	AC	7,529	6/1/2004	61	0	66	34	L&T Cracking, Swelling, Weathering
TBOT	03	AC	27,004	8/4/2009	100	0	0	100	Swelling
TBOT	04	AC	88,287	8/4/2009	99	0	100	0	L&T Cracking
TBOT	05	AC	16,466	8/4/2009	100	0	0	0	No distress

Table 1. 2022 pavement evaluation results (continued).

Branch	Section	Surface Type	Section Area (sf)	LCD	2022 PCI	% Distress Due to Load	% Distress Due to Climate/Durability	% Distress Due to Other	Type of Distress
TBOT	06	APC	24,230	6/1/2015	64	15	62	23	Alligator Cracking, Depression, L&T Cracking, Patching, Weathering
TBOT	07	PCC	25,868	6/3/2018	96	0	41	59	Corner Spalling, Joint Spalling, Joint Seal Damage, Shrinkage Cracking

Table Notes:

1. See Figure 3 for the location of the branch and section.
2. Surface Type: AC = asphalt cement concrete; AAC = asphalt overlay on AC; PCC = portland cement concrete; APC = asphalt overlay on PCC.
3. LCD = last construction date.
4. Distress due to load includes distress types that are attributed to a structural deficiency in the pavement, such as alligator cracking or rutting on asphalt-surfaced pavements or shattered slabs on PCC pavements.
5. Distress due to climate or durability includes distress types that are attributed to either the aging of the pavement and the effects of the environment (such as weathering, raveling, or block cracking on asphalt-surfaced pavements) or to a materials-related problem (such as durability cracking or alkali-silica reaction [ASR] on PCC pavements). If materials-related distresses were recorded during the inspection, further laboratory testing is required to definitively determine the type present.
6. Distress due to other refers to distress types that are not attributed to one factor but rather may be caused by a combination of factors.
7. Distress types are defined by ASTM D5340-20. L&T Cracking = Longitudinal and Transverse Cracking; LTD Cracking = Longitudinal, Transverse, and Diagonal Cracking; ASR = Alkali-Silica Reaction.

Inspection Comments

Ottumwa Regional Airport was inspected on November 14-15, 2022. There were thirty-three pavement sections defined during the inspection. Suspected alkali-silica reaction (ASR) was recorded at this airport in accordance with ASTM D5340-20. It should be noted that laboratory testing in the form of petrographic analysis is the only definitive way to validate the presence of ASR; however, the formation of a precipitate is evidence of a reaction consistent with this type of materials-related distress.

Runways

Runway 04/22 was defined by four sections. Section 01 contained areas of low-severity, unsealed joint reflection cracking. Section 02 was in excellent condition with low-severity, unsealed joint reflection cracking noted during the inspection. Section 03 was in excellent condition with no distress observed at the time of inspection. Section 04 was also in excellent condition with only low-severity ASR and joint seal damage recorded.

Runway 13/31 was defined by one section in excellent condition. Low-severity joint seal damage and longitudinal, transverse, and diagonal (LTD) cracking; low- and medium-severity joint spalling; and shrinkage cracking were noted in Section 01 during the inspection.

Taxiways

Taxiway A was defined by eight sections. Section 01 contained areas of low- and medium-severity longitudinal and transverse (L&T) cracking, medium-severity raveling, and low-severity weathering. Section 02 was in poor condition with areas of medium- and high-severity alligator cracking, low- and medium-severity L&T cracking, high-severity patching, and low-severity weathering recorded. Low- and medium-severity L&T cracking and low-severity alligator cracking, depression, rutting, and weathering were observed in Section 03. Section 04 contained all severities of L&T cracking and low-severity raveling, weathering, and alligator cracking. Low- and medium-severity weathering and low-severity alligator cracking, L&T cracking, patching, and swelling were identified in Section 05. Section 06 was in poor condition with low-severity weathering and block cracking; medium-severity alligator cracking and joint reflection cracking; and low- and medium-severity L&T cracking and swelling noted at the time of inspection. The low-severity cracking in Sections 01 through 06 was unsealed, and the medium-severity cracking was due to either the development of secondary cracking, unsatisfactory crack sealant, or unsealed crack widths that exceeded $\frac{1}{4}$ in. Section 07 was in excellent condition with only low-severity joint seal damage identified throughout. Section 08 was also in excellent condition with shrinkage cracking and low-severity joint seal damage and joint spalling recorded.

Taxiway B was defined by seven sections. Section 01 was in poor condition with medium-severity joint reflection cracking and alligator cracking, low- and medium-severity block cracking, all severities of L&T cracking, and low-severity weathering recorded. Section 02 contained areas of low- and medium-severity L&T cracking, swelling, and weathering. Section 03 was in excellent condition with low-severity swelling noted during the inspection. Section 04 was also in excellent condition with low-severity, unsealed L&T cracking identified. Additionally, Section 05 was in excellent condition with no distress noted at the time of inspection. Low-severity patching, depression, and weathering; medium-severity alligator cracking; and low- and medium-severity L&T cracking were observed in Section 06. The low-severity cracking in Sections 01, 02, 04, and 06 was both sealed and unsealed, and the medium-

severity cracking was due to either the development of secondary cracking, unsatisfactory crack sealant, or unsealed crack widths greater than $\frac{1}{4}$ in. Section 07 was in excellent condition with low- and medium-severity corner spalling, low-severity joint seal damage, medium-severity joint spalling, and shrinkage cracking noted during the inspection.

Aprons

Apron 01 was defined by nine sections. Section 01 was in poor condition with low-severity patching and shoving; medium-severity weathering and block cracking; medium- and high-severity alligator cracking; and low- and medium-severity swelling noted during the inspection. Section 02 was also in poor condition with low-severity swelling, depression, and weathering; medium-severity alligator cracking and joint reflection cracking; and low- and medium-severity block cracking recorded. Section 03 was in excellent condition with low-severity joint seal damage and medium-severity joint spalling identified during the inspection. Section 04 was in poor condition with medium-severity alligator cracking, joint reflection cracking, and block cracking; low- and medium-severity depression, L&T cracking, and swelling; and low-severity weathering. Section 05 was also in poor condition with medium-severity alligator cracking, block cracking, joint reflection cracking, and weathering observed during the inspection. The low-severity cracking in Sections 01, 02, 04, and 05 was unsealed, and the medium-severity cracking was due to either the development of secondary cracking, unsatisfactory crack sealant, or unsealed crack widths that exceeded $\frac{1}{4}$ in. Areas of medium-severity corner spalling, low- and medium-severity joint seal damage, and low-severity blow-up and LTD cracking were identified in Section 06. Section 07 was in excellent condition with only an isolated area of medium-severity joint spalling identified. Section 08 was also in excellent condition with low-severity corner break and low- and medium-severity joint seal damage noted during the inspection. An atypical area of medium-severity joint spalling and corner spalling was observed and recorded as an additional sample unit in accordance with ASTM D5340-20. Additionally, Section 09 was in excellent condition with no distress observed at the time of inspection.

Apron 02 was defined by four sections. Section 01 was in poor condition with medium-severity joint reflection cracking and alligator cracking, low- and medium-severity block cracking, and low-severity weathering recorded. Section 02 contained areas of low-severity raveling, depression, and rutting; low- and medium-severity weathering; medium-severity alligator cracking; and all severities of L&T cracking. The low-severity cracking in Sections 01 and 02 was unsealed, and the medium-severity cracking was due to either the development of secondary cracking, unsatisfactory crack sealant, or unsealed crack widths greater than $\frac{1}{4}$ in. Section 03 was in poor condition with medium-severity patching and alligator cracking, low- and medium-severity L&T cracking, and low-severity weathering observed at the time of inspection. Areas of medium-severity alligator cracking, low- and medium-severity L&T cracking, and low-severity weathering were observed in Section 04.

PAVEMENT MAINTENANCE AND REHABILITATION PROGRAM

Using the information collected during the pavement inspection, the PAVER pavement management software was used to develop a 5-year M&R program for Ottumwa Regional Airport. In addition, a 1-year plan for localized preventive maintenance (such as crack sealing and patching) was prepared.

Analysis Parameters

Critical PCIs

PAVER uses critical PCIs to determine whether localized preventive maintenance or major rehabilitation is the appropriate repair action. Above the critical PCI, localized preventive maintenance activities are recommended. Below the critical PCI, major rehabilitation actions, such as an overlay or reconstruction, are recommended. The Iowa DOT set the critical PCIs at 65 for runways, 60 for taxiways, and 55 for aprons.

Localized Preventive Maintenance Policies and Unit Costs

Localized preventive maintenance policies were developed for asphalt-surfaced and PCC pavements. These policies, shown in Appendix E, identify the localized preventive maintenance actions that the Iowa DOT considered appropriate to correct the different distress types and severities. The Iowa DOT provided unit costs for each of the localized preventive maintenance actions included in these policies, and these costs are detailed in Appendix E. Please note that this information is of a general nature for the entire state. The localized preventive maintenance policies and unit costs may require adjustment to reflect specific conditions at Ottumwa Regional Airport.

Major Rehabilitation Unit Costs

PAVER estimates the cost of major rehabilitation based on the predicted PCI of the pavement section. The Iowa DOT provided the costs for major rehabilitation, and they are presented in Appendix E. If major rehabilitation is recommended in the 5-year program, further engineering investigation will be needed to identify the most appropriate rehabilitation action and to estimate the cost of such work more accurately.

Budget and Inflation Rate

An unlimited budget with a start date of July 1, 2023 and an inflation rate of 4.0 percent was used during the analysis.

Analysis Approach

The 5-year M&R program was prepared with the goal of maintaining the pavements above established critical PCIs. During this analysis, major rehabilitation was recommended for pavements in the year they dropped below their critical PCI. For the first year (2023) of the analysis only, a localized preventive maintenance plan was developed for those pavement sections that were above their critical PCI. If major rehabilitation was triggered for a section in 2024 or 2025, then localized preventive maintenance was not recommended for 2023. While localized preventive maintenance should be an annual undertaking at Ottumwa Regional Airport, it is not possible to accurately predict the propagation of cracking and other distress types. Therefore, the airport should budget for maintenance every year and can use the 2023 localized

preventive maintenance plan as a baseline for that work. As the pavements age, it can be assumed that the amount of localized preventive maintenance required will increase.

Analysis Results

A summary of the M&R program for Ottumwa Regional Airport is presented in Table 2. Detailed information on the recommended localized preventive maintenance plan for 2023 is provided in Appendix F.

Table 2. 5-year M&R program under an unlimited funding analysis scenario.

Year	Branch	Section	Surface Type	Type of Repair	Estimated Cost
2023	A01OT	01	AAC	Major Rehabilitation	\$221,278
2023	A01OT	02	APC	Major Rehabilitation	\$384,395
2023	A01OT	03	PCC	Preventive Maintenance	\$697
2023	A01OT	04	APC	Major Rehabilitation	\$137,560
2023	A01OT	05	APC	Major Rehabilitation	\$105,099
2023	A01OT	06	PCC	Preventive Maintenance	\$8,943
2023	A01OT	07	PCC	Preventive Maintenance	\$553
2023	A01OT	08	PCC	Preventive Maintenance	\$3,061
2023	A02OT	01	APC	Major Rehabilitation	\$770,316
2023	A02OT	02	AC	Major Rehabilitation	\$418,296
2023	A02OT	03	APC	Major Rehabilitation	\$60,594
2023	A02OT	04	APC	Major Rehabilitation	\$16,128
2023	R13OT	01	PCC	Preventive Maintenance	\$2,425
2023	TAOT	01	AC	Preventive Maintenance	\$3,680
2023	TAOT	02	AC	Major Rehabilitation	\$70,408
2023	TAOT	03	AC	Major Rehabilitation	\$350,948
2023	TAOT	04	AAC	Major Rehabilitation	\$38,061
2023	TAOT	06	APC	Major Rehabilitation	\$908,287
2023	TBOT	01	APC	Major Rehabilitation	\$252,527
2023	TBOT	02	AC	Major Rehabilitation	\$38,548
2023	TBOT	07	PCC	Preventive Maintenance	\$403
2025	TBOT	06	APC	Major Rehabilitation	\$134,178

Total Estimated Cost: \$3,927,000

Table Notes:

1. See Figure 3 for the location of the branch and section.
2. Surface Type: AC = asphalt cement concrete; AAC = asphalt overlay on AC; PCC = portland cement concrete; APC = asphalt overlay on PCC.
3. Type of Repair: Major Rehabilitation such as pavement reconstruction or an overlay; Localized Preventive Maintenance such as crack sealing or patching.
4. The estimated costs provided are of a general nature for the entire state and may require adjustment to reflect specific conditions at Ottumwa Regional Airport.

The recommendations made in this report are based on a broad network-level analysis and meant to provide Ottumwa Regional Airport with an indication of the type of pavement-related work required during the next 5 years. Further engineering investigation may be necessary to identify which repair action is most appropriate. In addition, the cost estimates provided are based on overall unit costs for the entire state, and Ottumwa Regional Airport should adjust the plan to reflect local costs.

Because an unlimited budget was used in the analysis, it is possible that the pavement repair program may need to be adjusted to consider economic or operational constraints. The identification of a project need does not necessarily mean that state or federal funding will be available in the year it is indicated. It is important to remember that regardless of the recommendations presented within this report, Ottumwa Regional Airport is responsible for repairing pavements where existing conditions pose a hazard to safe operations.

General Maintenance Recommendations

In addition to the specific maintenance actions presented in Appendix F, it is recommended that the following strategies be considered for prolonging pavement life:

1. Regularly inspect all safety areas of the airport and document all inspection activity. A sample form that can be used to perform these inspections is provided in Table 3 of this report.
2. Provide a method of tracking all maintenance activities that occur as a result of inspections. These need to be reported to the FAA and the Iowa DOT. This information is used to update the APMS records and is required to remain in compliance with Public Law 103-305 (see the next section of this report for further information on this law).
3. Conduct an aggressive campaign against weed growth through timely herbicide applications and mowing programs of the safety areas. Vegetation growth in pavement cracks is destructive and significantly increases the rate of pavement deterioration.
4. Implement a periodic crack and joint sealing program. Keeping water and debris out of the pavement system by sealing cracks and joints is a proven and cost-effective method of extending the life of the pavement system.
5. Ensure that dirt does not build up along the edges of the pavements. This can create a “bathtub” effect, reducing the ability of water to drain away from the pavement system.
6. Closely monitor the movement of heavy equipment (particularly farming, construction, and fueling equipment) to make sure it is only operating on pavements that are designed to accommodate heavy loads. Failure to restrict heavy equipment to appropriate areas may result in the premature failure of airport pavements.

FAA Requirements (Public Law 103-305)

Because Ottumwa Regional Airport is in the National Plan of Integrated Airport Systems (NPIAS), the airport sponsor is required to keep the airport in a viable operating condition. This includes maintaining airport pavements in accordance with Public Law 103-305. Public Law 103-305 states that after January 1, 1995, NPIAS airport sponsors must provide assurances or certifications that an airport has implemented an effective airport pavement maintenance management system (PMMS) before the airport will be considered for federal funding of pavement replacement or reconstruction projects. To be in full compliance with the federal law,

the PMMS must include the following components at minimum: pavement inventory, pavement inspections, record keeping, information retrieval, and program funding.

This report serves as a complete pavement inventory and detailed inspection. To remain in compliance with the law, Ottumwa Regional Airport will also need to undertake monthly drive-by inspections of pavement conditions and track pavement-related maintenance activities.

FAA Advisory Circular 150/5380-7B provides detailed guidance pertaining to the requirements for an acceptable pavement management program (PMP). Appendix A of the FAA Advisory Circular 150/5380-7B outlines what needs to be included in a PMP to remain in compliance with this law and Grant Assurance #11. The following is a copy of this Appendix, along with instructions for supplementing this report so that all requirements are met. Note that the italicized words are direct quotations from the FAA Advisory Circular.

FAA Advisory Circular 150/5830-7B, Appendix A. Pavement Management Program (PMP)

A-1.0. *An effective PMP specifies the procedures to follow to assure that proper preventative and remedial pavement maintenance is performed. The program should identify funding or anticipated funding and other resources available to provide remedial and preventive maintenance activities. An airport sponsor may use any format deemed appropriate, but the program needs to, as a minimum, include the following:*

A-1.1. Pavement Inventory. *The following must be depicted:*

- a. Identification of all runways, taxiways, and aprons with pavement broken down into sections each having similar properties.*

The network definition map provided in Figure 3 of this report shows the location of all runways, taxiways, and aprons at Ottumwa Regional Airport. If any new pavements are constructed or any pavement areas are permanently closed, this map must be updated. Project plans should be submitted to the Iowa DOT after project completion.

- b. Dimensions of pavement sections.*

The dimensions of all runways, taxiways, and aprons are stored in the PAVER database. Appendix C provides information on length, width, and area. In addition, the network definition map provided in Figure 3 is drawn to scale. Any changes to pavement dimensions must be recorded.

- c. Type of pavement surface.*

The type of pavement for each section at Ottumwa Regional Airport is listed in Table 1 of this report and is also stored in the PAVER database. Any changes to the pavement type (through an overlay or reconstruction) must be recorded.

- d. Year of construction and/or most recent major rehabilitation.*

Dates for pavement construction, rehabilitation, or reconstruction must be recorded. The current pavement history for Ottumwa Regional Airport is provided in Appendix D of this report.

- e. *Whether AIP [Airport Improvement Program] or PFC [Passenger Facility Charge] funds were used to construct, reconstruct, or repair the pavement.*

Funding sources for all pavement projects should be recorded.

A-1.2. PMP Pavement Inspection Schedule. *Airports must perform a detailed inspection of airfield pavements at least once a year for the PMP. If a pavement condition index (PCI) survey is performed, as set forth in ASTM D5340, Standard Test Method for Airport Pavement Condition Index Surveys, the frequency of the detailed inspection by PCI surveys may be extended to three years. Less comprehensive routine daily, weekly, and monthly maintenance inspections required for operations should be addressed.*

This report consists of a detailed inspection that will extend the inspection period to 3 years. It is the airport sponsor's responsibility to perform monthly drive-by inspections. A sample pavement inspection report form is provided in Table 3 of this report.

A-1.3. Record Keeping. *The airport must record and keep on file complete information about all detailed inspections and maintenance performed until the pavement system is replaced. The types of distress, their locations, and remedial action, scheduled or performed, must be documented. The minimum information recorded includes:*

- a. *Inspection date*
- b. *Location*
- c. *Distress types*
- d. *Maintenance scheduled or performed*

Items a through c are satisfied by this inspection report. Item d is the responsibility of the airport, as is record keeping of the monthly drive-by inspections.

A-1.4. Information Retrieval. *An airport sponsor may use any form of record keeping it deems appropriate so long as the information and records from the pavement survey can generate required reports, as necessary.*

Keep this report, monthly drive-by inspection reports, construction updates, and all records of maintenance activities in a readily accessible location so that they can be easily retrieved as requested by the FAA.

Table 3. Pavement inspection report.

Inspected By: _____

Date Inspected: _____

Branch	Section	Distress Description/Dimensions/Severity/ Recommended Action	Description of Repair	Date Performed	Cost	Funding Source
A01OT	01					
A01OT	02					
A01OT	03					
A01OT	04					
A01OT	05					
A01OT	06					

Table 3. Pavement inspection report (continued).

Inspected By: _____

Date Inspected: _____

Branch	Section	Distress Description/Dimensions/Severity/ Recommended Action	Description of Repair	Date Performed	Cost	Funding Source
A01OT	07					
A01OT	08					
A01OT	09					
A02OT	01					
A02OT	02					
A02OT	03					

Table 3. Pavement inspection report (continued).

Inspected By: _____

Date Inspected: _____

Branch	Section	Distress Description/Dimensions/Severity/ Recommended Action	Description of Repair	Date Performed	Cost	Funding Source
A02OT	04					
R04OT	01					
R04OT	02					
R04OT	03					
R04OT	04					
R13OT	01					

Table 3. Pavement inspection report (continued).

Inspected By: _____

Date Inspected: _____

Branch	Section	Distress Description/Dimensions/Severity/ Recommended Action	Description of Repair	Date Performed	Cost	Funding Source
TAOT	01					
TAOT	02					
TAOT	03					
TAOT	04					
TAOT	05					
TAOT	06					

Table 3. Pavement inspection report (continued).

Inspected By: _____

Date Inspected: _____

Branch	Section	Distress Description/Dimensions/Severity/ Recommended Action	Description of Repair	Date Performed	Cost	Funding Source
TAOT	07					
TAOT	08					
TBOT	01					
TBOT	02					
TBOT	03					
TBOT	04					

Table 3. Pavement inspection report (continued).

Inspected By: _____

Date Inspected: _____

Branch	Section	Distress Description/Dimensions/Severity/ Recommended Action	Description of Repair	Date Performed	Cost	Funding Source
TBOT	05					
TBOT	06					
TBOT	07					

Table Note: See Figure 3 for the location of the branch and section.

SUMMARY

This report documents the results of the pavement evaluation conducted at Ottumwa Regional Airport. A visual inspection of the pavements in 2022 found that the overall condition of the pavement network is a PCI of 82. A 5-year pavement repair program, shown in Table 2, was generated for Ottumwa Regional Airport, which revealed that approximately \$3,927,000 needs to be expended on M&R. Ottumwa Regional Airport should utilize these study results to assist in planning for future maintenance needs as part of the airport CIP planning process.

APPENDIX A

CAUSE OF DISTRESS TABLES

Table A-1. Cause of pavement distress, asphalt-surfaced pavements.

Distress Type	Probable Cause of Distress
Alligator Cracking	Fatigue failure of the asphalt surface under repeated traffic loading.
Bleeding	Excessive amounts of asphalt cement or tars in the mix or low air void content, or both.
Block Cracking	Shrinkage of the asphalt and daily temperature cycling; it is not load associated.
Corrugation	Traffic action combined with an unstable pavement layer.
Depression	Settlement of the foundation soil or can be “built up” during construction.
Jet-Blast Erosion	Bituminous binder has been burned or carbonized.
Joint Reflection Cracking	Movement of the concrete slab beneath the asphalt surface due to thermal and moisture changes.
L&T Cracking	Cracks may be caused by (1) a poorly constructed paving lane joint, (2) shrinkage of the asphalt surface due to low temperatures or hardening of the asphalt, or (3) reflective cracking caused by cracks in an underlying PCC slab.
Oil Spillage	Deterioration or softening of the pavement surface caused by the spilling of oil, fuel, or other solvents.
Patching	N/A
Polished Aggregate	Repeated traffic applications.
Raveling	Asphalt binder may have hardened significantly, causing coarse aggregate pieces to dislodge.
Rutting	Usually caused by consolidation or lateral movement of the materials due to traffic loads.
Shoving	Where PCC pavements adjoin flexible pavements, PCC “growth” may shove the asphalt pavement.
Slippage Cracking	Low strength surface mix or poor bond between the surface and the next layer of the pavement structure.
Swelling	Usually caused by frost action or by swelling soil.
Weathering	Asphalt binder and/or fine aggregate may wear away as the pavement ages and hardens.

Table A-2. Cause of pavement distress, PCC pavements.

Distress Type	Probable Cause of Distress
ASR	Chemical reaction of alkalis in the portland cement with certain reactive silica minerals. ASR may be accelerated by the use of chemical pavement deicers.
Blowup	Incompressible materials in the joints.
Corner Break	Load repetition combined with loss of support and curling stresses.
Durability Cracking	Concrete's inability to withstand environmental factors such as freeze-thaw cycles.
Faulting	Upheaval or consolidation.
Joint Seal Damage	Stripping of joint sealant, extrusion of joint sealant, weed growth, hardening of the filler (oxidation), loss of bond to the slab edges, or absence of sealant in the joint.
LTD Cracking	Combination of load repetition, curling stresses, and shrinkage stresses.
Patching (Small and Large)	N/A
Popouts	Freeze-thaw action in combination with expansive aggregates.
Pumping	Poor drainage, poor joint sealant.
Scaling	Over finishing of concrete, deicing salts, improper construction, freeze-thaw cycles, and poor aggregate.
Shattered Slab	Load repetition.
Shrinkage Cracking	Setting and curing of the concrete.
Spalling (Joint and Corner)	Excessive stresses at the joint caused by infiltration of incompressible materials or traffic loads; weak concrete at the joint combined with traffic loads.

APPENDIX B

INSPECTION PHOTOGRAPHS

A01OT-01. Overview.



A01OT-01. Alligator Cracking (Sample Unit No. 02).



A01OT-02. Overview.



A01OT-02. Block Cracking (Sample Unit No. 06).



A01OT-03. Overview.



A01OT-03. Joint Seal Damage (Sample Unit No. 10).



A01OT-03. Joint Spalling (Sample Unit No. 05).



A01OT-04. Overview.



A01OT-04. Swelling (Sample Unit No. 01).



A01OT-05. Overview.



A01OT-05. Alligator Cracking (Sample Unit No. 01).



A01OT-06. Overview.



A01OT-06. Blow-Up (Sample Unit No. 12).



A01OT-07. Overview.



A01OT-07. Joint Spalling (Sample Unit No. 04).



A01OT-08. Overview.



A01OT-08. Corner Break (Sample Unit No. 12).



A01OT-08. Joint Spalling (Additional Sample Unit No. 13).



A01OT-09. Overview.



A02OT-01. Overview.



A02OT-01. Block Cracking (Sample Unit No. 09).



A02OT-02. Overview.



A02OT-02. Alligator Cracking (Sample Unit No. 04).



A02OT-03. Overview.



A02OT-03. L&T Cracking (Sample Unit No. 01).



A02OT-04. Overview.



A02OT-04. Alligator Cracking (Sample Unit No. 01).



A02OT-04. L&T Cracking (Sample Unit No. 01).



R04OT-01. Overview.



R04OT-02. Overview.



R04OT-02. Joint Reflection Cracking (Sample Unit No. 65).



R04OT-03. Overview.



R04OT-04. Overview.



R13OT-01. Overview.



R13OT-01. Joint Spalling (Sample Unit No. 183).



TAOT-01. Overview.



TAOT-01. L&T Cracking (Sample Unit No. 04).



TAOT-01. Weathering (Sample Unit No. 04).



TAOT-02. Overview.



TAOT-02. Alligator Cracking (Sample Unit No. 01).



TAOT-02. L&T Cracking (Sample Unit No. 01).



TAOT-02. Weathering (Sample Unit No. 01).



TAOT-03. Overview.



TAOT-03. Rutting (Sample Unit No. 11).



TAOT-04. Overview.



TAOT-04. L&T Cracking (Sample Unit No. 01).



TAOT-04. Weathering (Sample Unit No. 01).



TAOT-05. Overview.



TAOT-05. Swelling (Sample Unit No. 01).



TAOT-06. Overview.



TAOT-06. Alligator Cracking (Sample Unit No. 14).



TAOT-06. Block Cracking (Sample Unit No. 06).



TAOT-06. Weathering (Sample Unit No. 06).



TAOT-07. Overview.



TAOT-07. Joint Seal Damage (Sample Unit No. 16).



TAOT-08. Overview.



TAOT-08. Joint Spalling (Sample Unit No. 02).



TBOT-01. Overview.



TBOT-01. Block Cracking (Sample Unit No. 02).



TBOT-02. Overview.



TBOT-02. Swelling (Sample Unit No. 02).



TBOT-03. Overview.



TBOT-04. Overview.



TBOT-04. L&T Cracking (Sample Unit No. 05).



TBOT-05. Overview.



TBOT-06. Overview.



TBOT-06. Depression (Sample Unit No. 02).



TBOT-06. Patching (Additional Sample Unit No. 01).



TBOT-07. Overview.



APPENDIX C

INSPECTION REPORT

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 1

Branch - Section ID: A01OT - 001

Branch Name: NORTHEAST APRON

Use: APRON

LCD: 6/1/2007

PCI Family: IowaAACAPSouthern

Surface Type: AAC

Rank: P

Section Area (sf): 20,450.00

Length (ft): 230.00

Width (ft): 100.00

From: .

To: .

Slabs:

Section Comments:

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 11/14/2022

Inspection Comments:

PCI: 33

Total Samples: 5

Surveyed: 4

Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 24

Sample Area (SF): 4,808.00

41 ALLIGATOR CRACKING	H	5.00 SF	
41 ALLIGATOR CRACKING	M	180.00 SF	
43 BLOCK CRACKING	M	4,611.00 SF	W, TYP. 7x7
50 PATCHING	L	12.00 SF	
54 SHOIVING	L	40.00 SF	
57 WEATHERING	M	4,796.00 SF	

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 25

Sample Area (SF): 5,490.00

41 ALLIGATOR CRACKING	M	190.00 SF	
43 BLOCK CRACKING	M	5,230.00 SF	
50 PATCHING	L	70.00 SF	
56 SWELLING	L	50.00 SF	
56 SWELLING	M	50.00 SF	
57 WEATHERING	M	5,420.00 SF	

Sample Number: 03

Sample Type: R

Sample Comments:

Sample PCI: 37

Sample Area (SF): 3,000.00

43 BLOCK CRACKING	M	3,000.00 SF	
54 SHOIVING	L	25.00 SF	
57 WEATHERING	M	3,000.00 SF	

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 51

Sample Area (SF): 4,850.00

43 BLOCK CRACKING	M	3,000.00 SF	
57 WEATHERING	M	4,850.00 SF	

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 2

Branch - Section ID: A01OT - 002

Branch Name: NORTHEAST APRON

Use: APRON

LCD: 6/30/1970
 Surface Type: APC
 Rank: P
 Section Area (sf): 35,525.00
 Length (ft): 400.00
 Width (ft): 87.00
 From: A01-01
 To: TA-06

PCI Family: IowaAPCAPall

Slabs:
 Slab Length (ft):
 Slab Width (ft):
 Joint Length (ft):

Section Comments:

Last Insp Date: 11/14/2022
 PCI: 29
 Total Samples: 9
 Surveyed: 4

Inspection Comments:

Sample Number: 02

Sample Type: R
 Sample PCI: 25
 Sample Area (SF): 4,350.00

Sample Comments:

41 ALLIGATOR CRACKING	M	35.00 SF	
43 BLOCK CRACKING	L	2,315.00 SF	LU TYP 7X7
43 BLOCK CRACKING	M	2,000.00 SF	
45 DEPRESSION	L	60.00 SF	
47 JOINT REFLECTION CRACKING	M	500.00 Ft	W, 2NDY, FS
57 WEATHERING	L	4,350.00 SF	

Sample Number: 04

Sample Type: R
 Sample PCI: 28
 Sample Area (SF): 4,350.00

Sample Comments:

43 BLOCK CRACKING	L	2,350.00 SF	
43 BLOCK CRACKING	M	2,000.00 SF	
47 JOINT REFLECTION CRACKING	M	500.00 Ft	W, FS
56 SWELLING	L	50.00 SF	
57 WEATHERING	L	4,350.00 SF	

Sample Number: 06

Sample Type: R
 Sample PCI: 30
 Sample Area (SF): 4,837.00

Sample Comments:

43 BLOCK CRACKING	L	2,175.00 SF	
43 BLOCK CRACKING	M	2,419.00 SF	
47 JOINT REFLECTION CRACKING	M	600.00 Ft	W, FS
57 WEATHERING	L	4,837.00 SF	

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 3

Sample Number: 08

Sample Type: R

Sample Comments:

Sample PCI: 31

Sample Area (SF): 5,070.00

43 BLOCK CRACKING	L	2,419.00 SF	
43 BLOCK CRACKING	M	2,535.00 SF	
47 JOINT REFLECTION CRACKING	M	500.00 Ft	FS W
57 WEATHERING	L	5,070.00 SF	

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 4

Branch - Section ID: A01OT - 003

Branch Name: NORTHEAST APRON

Use: APRON

LCD: 4/3/2021

PCI Family: IowaPCCAPSE_CommEnhanced

Surface Type: PCC

Rank: P

Section Area (sf): 38,700.00

Length (ft): 338.00

Width (ft): 114.00

From: A01OT-002

To: End of A01OT

Slabs: 387

Section Comments:

Slab Length (ft): 10.00

Slab Width (ft): 10.00

Joint Length (ft): 7,286.03

Last Insp Date: 11/15/2022

Inspection Comments:

PCI: 98

Total Samples: 17

Surveyed: 8

Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 24.00

65 JOINT SEAL DAMAGE

L

24.00 Slabs

Sample Number: 03

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 24.00

65 JOINT SEAL DAMAGE

L

24.00 Slabs

Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 95

Sample Area (Slabs): 24.00

65 JOINT SEAL DAMAGE

L

24.00 Slabs

74 JOINT SPALL

M

1.00 Slabs

Sample Number: 08

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 24.00

65 JOINT SEAL DAMAGE

L

24.00 Slabs

Sample Number: 10

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 24.00

65 JOINT SEAL DAMAGE

L

24.00 Slabs

Sample Number: 12

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 24.00

65 JOINT SEAL DAMAGE

L

24.00 Slabs

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 5

Sample Number: 14

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 24.00

65 JOINT SEAL DAMAGE

L

24.00 Slabs

Sample Number: 17

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 24.00

65 JOINT SEAL DAMAGE

L

24.00 Slabs

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 6

Branch - Section ID: A01OT - 004

Branch Name: NORTHEAST APRON

Use: APRON

LCD: 6/1/2007
 Surface Type: APC
 Rank: P
 Section Area (sf): 12,713.00
 Length (ft): 365.00
 Width (ft): 25.00
 From: .
 To: ..

PCI Family: IowaAPCAPall

Slabs:
 Slab Length (ft):
 Slab Width (ft):
 Joint Length (ft):

Section Comments:

Last Insp Date: 11/14/2022
 PCI: 32
 Total Samples: 3
 Surveyed: 3

Inspection Comments:

Sample Number: 01

Sample Type: R
 Sample PCI: 37
 Sample Area (SF): 3,910.00

Sample Comments:

41 ALLIGATOR CRACKING	M	5.00 SF	
45 DEPRESSION	L	55.00 SF	
48 LONGITUDINAL/TRANSVERSE CRACKING	L	201.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	M	350.00 Ft	W, 2NDY, FS
56 SWELLING	L	44.00 SF	
56 SWELLING	M	20.00 SF	
57 WEATHERING	L	3,910.00 SF	

Sample Number: 02

Sample Type: R
 Sample PCI: 23
 Sample Area (SF): 5,625.00

Sample Comments:

41 ALLIGATOR CRACKING	M	150.00 SF	
43 BLOCK CRACKING	M	3,938.00 SF	W
47 JOINT REFLECTION CRACKING	M	250.00 Ft	FS
48 LONGITUDINAL/TRANSVERSE CRACKING	L	126.00 Ft	LU
56 SWELLING	L	108.00 SF	
56 SWELLING	M	40.00 SF	

Sample Number: 03

Sample Type: R
 Sample PCI: 40
 Sample Area (SF): 3,178.00

Sample Comments:

45 DEPRESSION	M	5.00 SF	
48 LONGITUDINAL/TRANSVERSE CRACKING	L	125.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	M	470.00 Ft	W, 2NDY, FS
56 SWELLING	L	20.00 SF	
57 WEATHERING	L	3,178.00 SF	

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 7

Branch - Section ID: A01OT - 005

Branch Name: NORTHEAST APRON

Use: APRON

LCD: 1/1/1970 PCI Family: IowaAPCAPall

Surface Type: APC

Rank: P

Section Area (sf): 9,713.00

Length (ft): 250.00

Width (ft): 35.00

From: .

To: .

Slabs: Section Comments:

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 11/14/2022 Inspection Comments:

PCI: 26

Total Samples: 2

Surveyed: 2

Sample Number: 01

Sample Type: R Sample Comments:

Sample PCI: 16

Sample Area (SF): 4,403.00

41 ALLIGATOR CRACKING	M	290.00 SF	
43 BLOCK CRACKING	M	4,085.00 SF	FS,W, TYP 4x3
47 JOINT REFLECTION CRACKING	M	375.00 Ft	W, FS
57 WEATHERING	M	4,403.00 SF	

Sample Number: 02

Sample Type: R Sample Comments:

Sample PCI: 34

Sample Area (SF): 5,310.00

43 BLOCK CRACKING	M	5,310.00 SF	
47 JOINT REFLECTION CRACKING	M	375.00 Ft	W, FS
57 WEATHERING	M	5,310.00 SF	

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 8

Branch - Section ID: A01OT - 006

Branch Name: NORTHEAST APRON

Use: APRON

LCD: 8/3/2018

PCI Family: IowaPCCAPSE_CommEnhanced

Surface Type: PCC

Rank: P

Section Area (sf): 36,044.00

Length (ft): 445.00

Width (ft): 75.00

From: .

To: .

Slabs: 288

Section Comments:

Slab Length (ft): 12.50

Slab Width (ft): 10.00

Joint Length (ft): 5,926.34

Last Insp Date: 11/14/2022

Inspection Comments:

PCI: 93

Total Samples: 16

Surveyed: 6

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 15.00

65 JOINT SEAL DAMAGE

L

15.00 Slabs

75 CORNER SPALL

M

1.00 Slabs

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 18.00

65 JOINT SEAL DAMAGE

L

18.00 Slabs

Sample Number: 06

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 18.00

65 JOINT SEAL DAMAGE

M

18.00 Slabs

Sample Number: 10

Sample Type: R

Sample Comments:

Sample PCI: 89

Sample Area (Slabs): 18.00

63 LINEAR CRACKING

L

2.00 Slabs

65 JOINT SEAL DAMAGE

L

18.00 Slabs

Sample Number: 12

Sample Type: R

Sample Comments:

Sample PCI: 84

Sample Area (Slabs): 18.00

61 BLOW-UP

L

1.00 Slabs

65 JOINT SEAL DAMAGE

L

18.00 Slabs

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 9

Sample Number: 14

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 24.00

65 JOINT SEAL DAMAGE

L

24.00 Slabs

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 10

Branch - Section ID: A01OT - 007

Branch Name: NORTHEAST APRON

Use: APRON

LCD: 8/3/2019

PCI Family: IowaPCCAPSE_CommEnhanced

Surface Type: PCC

Rank: P

Section Area (sf): 34,176.00

Length (ft): 343.00

Width (ft): 100.00

From: .

To: .

Slabs: 342

Section Comments:

Slab Length (ft): 10.00

Slab Width (ft): 10.00

Joint Length (ft): 6,393.80

Last Insp Date: 11/14/2022

Inspection Comments:

PCI: 100

Total Samples: 17

Surveyed: 7

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 24.00

NO DISTRESS

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 97

Sample Area (Slabs): 24.00

74 JOINT SPALL

M

1.00 Slabs

Sample Number: 06

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 24.00

NO DISTRESS

Sample Number: 08

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 24.00

NO DISTRESS

Sample Number: 11

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 20.00

NO DISTRESS

Sample Number: 13

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 20.00

NO DISTRESS

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 11

Sample Number: 15

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 20.00

NO DISTRESS

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 12

Branch - Section ID: A01OT - 008

Branch Name: NORTHEAST APRON

Use: APRON

LCD: 8/3/2016

PCI Family: IowaPCCAPSE_CommEnhanced

Surface Type: PCC

Rank: P

Section Area (sf): 25,031.00

Length (ft): 280.00

Width (ft): 100.00

From: .

To: .

Slabs: 280

Section Comments:

Slab Length (ft): 10.00

Slab Width (ft): 10.00

Joint Length (ft): 5,220.00

Last Insp Date: 11/14/2022

Inspection Comments:

PCI: 95

Total Samples: 14

Surveyed: 7

Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE	L	20.00 Slabs
----------------------	---	-------------

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE	L	20.00 Slabs
----------------------	---	-------------

Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE	L	20.00 Slabs
----------------------	---	-------------

Sample Number: 08

Sample Type: R

Sample Comments:

Sample PCI: 94

Sample Area (Slabs): 20.00

62 CORNER BREAK	L	1.00 Slabs
65 JOINT SEAL DAMAGE	L	20.00 Slabs

Sample Number: 09

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE	L	20.00 Slabs
----------------------	---	-------------

Sample Number: 12

Sample Type: R

Sample Comments:

Sample PCI: 87

Sample Area (Slabs): 20.00

62 CORNER BREAK	L	2.00 Slabs
65 JOINT SEAL DAMAGE	M	20.00 Slabs

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 13

Sample Number: 13

Sample Type: A

Sample Comments:

Sample PCI: 90

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

74 JOINT SPALL

M

1.00 Slabs

75 CORNER SPALL

M

1.00 Slabs

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 14

Branch - Section ID: A01OT - 009

Branch Name: NORTHEAST APRON

Use: APRON

LCD: 4/3/2022

PCI Family: IowaPCCAPSE_CommEnhanced

Surface Type: PCC

Rank: P

Section Area (sf): 12,163.00

Length (ft): 338.00

Width (ft): 36.00

From: SEE MAP

To: SEE MAP

Slabs: 122

Section Comments:

Slab Length (ft): 10.00

Slab Width (ft): 10.00

Joint Length (ft): 2,058.75

Last Insp Date: 11/15/2022

Inspection Comments:

PCI: 100

Total Samples: 7

Surveyed: 4

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 20.00

NO DISTRESS

Sample Number: 03

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 20.00

NO DISTRESS

Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 20.00

NO DISTRESS

Sample Number: 06

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 20.00

NO DISTRESS

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 15

Branch - Section ID: A02OT - 001

Branch Name: TERMINAL APRON

Use: APRON

LCD: 6/30/1970
 Surface Type: APC
 Rank: P
 Section Area (sf): 71,191.00
 Length (ft): 700.00
 Width (ft): 75.00
 From: NORTH END OF TERM BLDG
 To: SOUTH END OF TERM BLDG

PCI Family: IowaAPCAPall

Slabs:
 Slab Length (ft):
 Slab Width (ft):
 Joint Length (ft):

Section Comments:

Last Insp Date: 11/14/2022
 PCI: 28
 Total Samples: 16
 Surveyed: 5

Inspection Comments:

Sample Number: 02

Sample Type: R
 Sample PCI: 23
 Sample Area (SF): 4,250.00

Sample Comments:

41 ALLIGATOR CRACKING	M	150.00 SF	
43 BLOCK CRACKING	L	3,100.00 SF	
43 BLOCK CRACKING	M	1,000.00 SF	
47 JOINT REFLECTION CRACKING	M	600.00 Ft	W, FS
57 WEATHERING	L	4,250.00 SF	

Sample Number: 04

Sample Type: R
 Sample PCI: 22
 Sample Area (SF): 4,250.00

Sample Comments:

41 ALLIGATOR CRACKING	M	200.00 SF	
43 BLOCK CRACKING	L	3,050.00 SF	LU TYP 5X5
43 BLOCK CRACKING	M	1,000.00 SF	
47 JOINT REFLECTION CRACKING	M	600.00 Ft	FS W
57 WEATHERING	L	4,250.00 SF	

Sample Number: 09

Sample Type: R
 Sample PCI: 32
 Sample Area (SF): 5,625.00

Sample Comments:

41 ALLIGATOR CRACKING	M	50.00 SF	
43 BLOCK CRACKING	L	4,575.00 SF	
43 BLOCK CRACKING	M	1,000.00 SF	
47 JOINT REFLECTION CRACKING	M	600.00 Ft	W, FS
57 WEATHERING	L	5,625.00 SF	

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 16

Sample Number: 11

Sample Type: R

Sample Comments:

Sample PCI: 29

Sample Area (SF): 4,500.00

41 ALLIGATOR CRACKING	M	50.00 SF	
43 BLOCK CRACKING	L	3,450.00 SF	
43 BLOCK CRACKING	M	1,000.00 SF	
47 JOINT REFLECTION CRACKING	M	600.00 Ft	W, FS
57 WEATHERING	L	4,500.00 SF	

Sample Number: 13

Sample Type: R

Sample Comments:

Sample PCI: 32

Sample Area (SF): 4,500.00

43 BLOCK CRACKING	L	3,500.00 SF	
43 BLOCK CRACKING	M	1,000.00 SF	
47 JOINT REFLECTION CRACKING	M	600.00 Ft	W, FS
57 WEATHERING	L	4,500.00 SF	

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 17

Branch - Section ID: A02OT - 002

Branch Name: TERMINAL APRON

Use: APRON

LCD: 8/11/2001 PCI Family: IowaACAPSouthern

Surface Type: AC

Rank: P

Section Area (sf): 79,574.00

Length (ft): 640.00

Width (ft): 140.00

From: A02OT-01

To: ..

Slabs: Section Comments:

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 11/14/2022 Inspection Comments:

PCI: 51

Total Samples: 17

Surveyed: 5

Sample Number: 04

Sample Type: R Sample Comments:

Sample PCI: 34

Sample Area (SF): 5,000.00

41 ALLIGATOR CRACKING	M	200.00 SF	
45 DEPRESSION	L	35.00 SF	
48 LONGITUDINAL/TRANSVERSE CRACKING	L	83.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	M	330.00 Ft	W, 2NDY, FS
53 RUTTING	L	115.00 SF	
57 WEATHERING	L	5,000.00 SF	

Sample Number: 06

Sample Type: R Sample Comments:

Sample PCI: 54

Sample Area (SF): 4,000.00

45 DEPRESSION	L	15.00 SF	
48 LONGITUDINAL/TRANSVERSE CRACKING	H	17.00 Ft	1 FT
48 LONGITUDINAL/TRANSVERSE CRACKING	M	336.00 Ft	W, 2NDY, FS
57 WEATHERING	L	4,000.00 SF	

Sample Number: 08

Sample Type: R Sample Comments:

Sample PCI: 65

Sample Area (SF): 5,000.00

45 DEPRESSION	L	30.00 SF	
48 LONGITUDINAL/TRANSVERSE CRACKING	M	262.00 Ft	W, 2NDY, FS
57 WEATHERING	L	5,000.00 SF	

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 18

Sample Number: 10

Sample Type: R

Sample Comments:

Sample PCI: 43

Sample Area (SF): 5,000.00

41 ALLIGATOR CRACKING	M	35.00 SF	
45 DEPRESSION	L	50.00 SF	
48 LONGITUDINAL/TRANSVERSE CRACKING	M	410.00 Ft	W, 2NDY, FS
52 RAVELING	L	30.00 SF	
53 RUTTING	L	45.00 SF	
57 WEATHERING	L	4,940.00 SF	
57 WEATHERING	M	30.00 SF	

Sample Number: 14

Sample Type: R

Sample Comments:

Sample PCI: 58

Sample Area (SF): 5,000.00

45 DEPRESSION	L	6.00 SF	
48 LONGITUDINAL/TRANSVERSE CRACKING	L	16.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	M	475.00 Ft	W, 2NDY, FS
57 WEATHERING	L	5,000.00 SF	

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 19

Branch - Section ID: A02OT - 003

Branch Name: TERMINAL APRON

Use: APRON

LCD: 2/11/1970

PCI Family: IowaAPCAPall

Surface Type: APC

Rank: P

Section Area (sf): 5,600.00

Length (ft): 160.00

Width (ft): 35.00

From: .

To: .

Slabs:

Section Comments:

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 11/14/2022

Inspection Comments:

PCI: 27

Total Samples: 1

Surveyed: 1

Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 27

Sample Area (SF): 5,600.00

41 ALLIGATOR CRACKING	M	325.00 SF
48 LONGITUDINAL/TRANSVERSE CRACKING	L	320.00 Ft
48 LONGITUDINAL/TRANSVERSE CRACKING	M	793.00 Ft
50 PATCHING	M	5.00 SF
57 WEATHERING	L	5,595.00 SF

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 20

Branch - Section ID: A02OT - 004

Branch Name: TERMINAL APRON

Use: APRON

LCD: 2/11/2012

PCI Family: IowaAPCAPall

Surface Type: APC

Rank: P

Section Area (sf): 3,150.00

Length (ft): 90.00

Width (ft): 35.00

From: SEE MAP

To: SEE MAP

Slabs:

Section Comments:

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 11/14/2022

Inspection Comments:

PCI: 55

Total Samples: 1

Surveyed: 1

Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 55

Sample Area (SF): 3,150.00

41 ALLIGATOR CRACKING	M	25.00 SF	edge
48 LONGITUDINAL/TRANSVERSE CRACKING	L	143.00 Ft	
48 LONGITUDINAL/TRANSVERSE CRACKING	M	177.00 Ft	
57 WEATHERING	L	3,150.00 SF	

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 21

Branch - Section ID: R04OT - 001

Branch Name: RUNWAY 04/22

Use: RUNWAY

LCD: 8/1/2009

PCI Family: IowaAPCRWSouthern

Surface Type: APC

Rank: S

Section Area (sf): 37,912.00

Length (ft): 554.00

Width (ft): 100.00

From: 04 APPROACH

To: RUNWAY 13/31

Slabs:

Section Comments:

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 11/14/2022

Inspection Comments:

PCI: 95

Total Samples: 8

Surveyed: 4

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (SF): 5,000.00

47 JOINT REFLECTION CRACKING L 129.00 Ft LU

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 94

Sample Area (SF): 5,000.00

47 JOINT REFLECTION CRACKING L 98.00 Ft LU

Sample Number: 06

Sample Type: R

Sample Comments:

Sample PCI: 95

Sample Area (SF): 5,000.00

47 JOINT REFLECTION CRACKING L 84.00 Ft LU

Sample Number: 07

Sample Type: R

Sample Comments:

Sample PCI: 97

Sample Area (SF): 5,000.00

47 JOINT REFLECTION CRACKING L 48.00 Ft LU

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 22

Branch - Section ID: R04OT - 002

Branch Name: RUNWAY 04/22

Use: RUNWAY

LCD: 8/1/2009 PCI Family: IowaAPCRWSouthern

Surface Type: APC

Rank: S

Section Area (sf): 322,356.00

Length (ft): 3,223.00

Width (ft): 100.00

From: RUNWAY 13/31

To: 22 APPROACH

Slabs: Section Comments:

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 11/14/2022 Inspection Comments:

PCI: 95

Total Samples: 65

Surveyed: 7

Sample Number: 11

Sample Type: R Sample Comments:

Sample PCI: 92

Sample Area (SF): 5,000.00

47 JOINT REFLECTION CRACKING L 148.00 Ft LU

Sample Number: 20

Sample Type: R Sample Comments:

Sample PCI: 98

Sample Area (SF): 5,000.00

47 JOINT REFLECTION CRACKING L 42.00 Ft LU

Sample Number: 30

Sample Type: R Sample Comments:

Sample PCI: 94

Sample Area (SF): 5,000.00

47 JOINT REFLECTION CRACKING L 105.00 Ft LU

Sample Number: 38

Sample Type: R Sample Comments:

Sample PCI: 92

Sample Area (SF): 5,000.00

47 JOINT REFLECTION CRACKING L 146.00 Ft LU

Sample Number: 47

Sample Type: R Sample Comments:

Sample PCI: 99

Sample Area (SF): 5,000.00

47 JOINT REFLECTION CRACKING L 21.00 Ft LU

Sample Number: 56

Sample Type: R Sample Comments:

Sample PCI: 98

Sample Area (SF): 5,000.00

47 JOINT REFLECTION CRACKING L 43.00 Ft LU

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 23

Sample Number: 65

Sample Type: R

Sample Comments:

Sample PCI: 90

Sample Area (SF): 4,500.00

47 JOINT REFLECTION CRACKING

L

200.00 Ft

LU

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 24

Branch - Section ID: R04OT - 003

Branch Name: RUNWAY 04/22

Use: RUNWAY

LCD: 8/4/2009

PCI Family: IowaACRWSouthern

Surface Type: AC

Rank: S

Section Area (sf): 49,829.00

Length (ft): 498.00

Width (ft): 100.00

From: .

To: .

Slabs:

Section Comments:

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 11/14/2022

Inspection Comments:

PCI: 100

Total Samples: 10

Surveyed: 5

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (SF): 5,000.00

NO DISTRESS

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (SF): 5,000.00

NO DISTRESS

Sample Number: 06

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (SF): 5,000.00

NO DISTRESS

Sample Number: 08

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (SF): 5,000.00

NO DISTRESS

Sample Number: 09

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (SF): 5,000.00

NO DISTRESS

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 25

Branch - Section ID: R04OT - 004

Branch Name: RUNWAY 04/22

Use: RUNWAY

LCD: 6/3/2018

PCI Family: IowaPCCRWSE_Enhanced

Surface Type: PCC

Rank: S

Section Area (sf): 40,000.00

Length (ft): 400.00

Width (ft): 100.00

From: .

To: .

Slabs: 256

Section Comments:

Slab Length (ft): 12.50

Slab Width (ft): 12.50

Joint Length (ft): 5,900.00

Last Insp Date: 11/14/2022

Inspection Comments:

PCI: 97

Total Samples: 12

Surveyed: 6

Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 90

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

76 ASR

L

2.00 Slabs

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 24.00

65 JOINT SEAL DAMAGE

L

24.00 Slabs

Sample Number: 08

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 09

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 12

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 24.00

65 JOINT SEAL DAMAGE

L

24.00 Slabs

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 26

Branch - Section ID: R13OT - 001

Branch Name: RUNWAY 13/31

Use: RUNWAY

LCD: 6/3/2018

PCI Family: IowaPCCRWSE_Enhanced

Surface Type: PCC

Rank: P

Section Area (sf): 601,045.00

Length (ft): 6,007.00

Width (ft): 100.00

From: 13 APPROACH

To: 31 APPROACH

Slabs: 3,847

Section Comments:

Slab Length (ft): 12.50

Slab Width (ft): 12.50

Joint Length (ft): 90,056.69

Last Insp Date: 11/14/2022

Inspection Comments:

PCI: 96

Total Samples: 194

Surveyed: 20

Sample Number: 003

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 006

Sample Type: R

Sample Comments:

Sample PCI: 94

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

74 JOINT SPALL

M

1.00 Slabs

Sample Number: 023

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 026

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 043

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 046

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 27

Sample Number: 063

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 066

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 083

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 086

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 103

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 106

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 123

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 126

Sample Type: R

Sample Comments:

Sample PCI: 94

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

73 SHRINKAGE CRACKING

N

1.00 Slabs

74 JOINT SPALL

L

2.00 Slabs

Sample Number: 143

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 28

Sample Number: 146

Sample Type: R

Sample Comments:

Sample PCI: 89

Sample Area (Slabs): 20.00

63 LINEAR CRACKING	L	1.00 Slabs
65 JOINT SEAL DAMAGE	L	20.00 Slabs
74 JOINT SPALL	L	3.00 Slabs

Sample Number: 163

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE	L	20.00 Slabs
----------------------	---	-------------

Sample Number: 166

Sample Type: R

Sample Comments:

Sample PCI: 90

Sample Area (Slabs): 20.00

63 LINEAR CRACKING	L	2.00 Slabs
65 JOINT SEAL DAMAGE	L	20.00 Slabs

Sample Number: 183

Sample Type: R

Sample Comments:

Sample PCI: 96

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE	L	20.00 Slabs
74 JOINT SPALL	L	1.00 Slabs

Sample Number: 186

Sample Type: R

Sample Comments:

Sample PCI: 92

Sample Area (Slabs): 20.00

63 LINEAR CRACKING	L	1.00 Slabs
65 JOINT SEAL DAMAGE	L	20.00 Slabs
74 JOINT SPALL	L	1.00 Slabs

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 29

Branch - Section ID: TAOT - 001

Branch Name: TAXIWAY A

Use: TAXIWAY

LCD: 6/1/2004

PCI Family: IowaACTWSouthern

Surface Type: AC

Rank: P

Section Area (sf): 59,790.00

Length (ft): 1,680.00

Width (ft): 35.00

From: RUNWAY 13/31

To: TAXIWAY B

Slabs:

Section Comments:

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 11/14/2022

Inspection Comments:

PCI: 73

Total Samples: 13

Surveyed: 5

Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 75

Sample Area (SF): 5,600.00

48 LONGITUDINAL/TRANSVERSE CRACKING	L	180.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	M	35.00 Ft	W
52 RAVELING	M	1.00 SF	
57 WEATHERING	L	5,599.00 SF	

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 72

Sample Area (SF): 4,375.00

48 LONGITUDINAL/TRANSVERSE CRACKING	L	30.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	M	155.00 Ft	W
57 WEATHERING	L	4,375.00 SF	

Sample Number: 06

Sample Type: R

Sample Comments:

Sample PCI: 76

Sample Area (SF): 4,375.00

48 LONGITUDINAL/TRANSVERSE CRACKING	L	50.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	M	80.00 Ft	2NDY
57 WEATHERING	L	4,375.00 SF	

Sample Number: 08

Sample Type: R

Sample Comments:

Sample PCI: 70

Sample Area (SF): 4,375.00

48 LONGITUDINAL/TRANSVERSE CRACKING	L	47.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	M	105.00 Ft	2NDY
52 RAVELING	M	1.00 SF	
57 WEATHERING	L	4,374.00 SF	

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 30

Sample Number: 11

Sample Type: R

Sample Comments:

Sample PCI: 70

Sample Area (SF): 4,460.00

48 LONGITUDINAL/TRANSVERSE CRACKING	L	51.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	M	160.00 Ft	W, 2NDY
57 WEATHERING	L	4,460.00 SF	

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 31

Branch - Section ID: TAOT - 002

Branch Name: TAXIWAY A

Use: TAXIWAY

LCD: 5/1/2004

PCI Family: IowaACTWSouthern

Surface Type: AC

Rank: P

Section Area (sf): 6,507.00

Length (ft): 145.00

Width (ft): 35.00

From: RW13OT-01

To: TWBOT-02

Slabs:

Section Comments:

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 11/14/2022

Inspection Comments:

PCI: 39

Total Samples: 1

Surveyed: 1

Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 39

Sample Area (SF): 6,507.00

41 ALLIGATOR CRACKING	H	9.00 SF	
41 ALLIGATOR CRACKING	M	42.00 SF	
48 LONGITUDINAL/TRANSVERSE CRACKING	L	475.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	M	289.00 Ft	FS
50 PATCHING	H	200.00 SF	EDGE
57 WEATHERING	L	6,307.00 SF	

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 32

Branch - Section ID: TAOT - 003

Branch Name: TAXIWAY A

Use: TAXIWAY

LCD: 8/4/2002 PCI Family: IowaACTWSouthern

Surface Type: AC

Rank: P

Section Area (sf): 68,546.00

Length (ft): 1,977.00

Width (ft): 35.00

From: RW04OT-02

To: RW13OT-01

Slabs: Section Comments:

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 11/14/2022 Inspection Comments:

PCI: 57

Total Samples: 16

Surveyed: 5

Sample Number: 03

Sample Type: R Sample Comments:

Sample PCI: 65

Sample Area (SF): 4,375.00

41 ALLIGATOR CRACKING	L	22.00 SF	edge
48 LONGITUDINAL/TRANSVERSE CRACKING	L	181.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	M	133.00 Ft	W, 2NDY
57 WEATHERING	L	4,375.00 SF	

Sample Number: 05

Sample Type: R Sample Comments:

Sample PCI: 53

Sample Area (SF): 4,375.00

41 ALLIGATOR CRACKING	L	139.00 SF	edge
48 LONGITUDINAL/TRANSVERSE CRACKING	L	97.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	M	125.00 Ft	2NDY
57 WEATHERING	L	4,375.00 SF	

Sample Number: 07

Sample Type: R Sample Comments:

Sample PCI: 58

Sample Area (SF): 4,375.00

41 ALLIGATOR CRACKING	L	89.00 SF	edge
48 LONGITUDINAL/TRANSVERSE CRACKING	L	79.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	M	151.00 Ft	W
57 WEATHERING	L	4,375.00 SF	

Sample Number: 09

Sample Type: R Sample Comments:

Sample PCI: 52

Sample Area (SF): 4,375.00

41 ALLIGATOR CRACKING	L	76.00 SF	edge
48 LONGITUDINAL/TRANSVERSE CRACKING	L	167.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	M	171.00 Ft	W, 2NDY, FS
53 RUTTING	L	100.00 SF	
57 WEATHERING	L	4,375.00 SF	

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 33

Sample Number: 11

Sample Type: R

Sample Comments:

Sample PCI: 59

Sample Area (SF): 4,375.00

45 DEPRESSION	L	40.00 SF	
48 LONGITUDINAL/TRANSVERSE CRACKING	L	250.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	M	131.00 Ft	W, 2NDY
53 RUTTING	L	150.00 SF	
57 WEATHERING	L	4,375.00 SF	

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 34

Branch - Section ID: TAOT - 004

Branch Name: TAXIWAY A

Use: TAXIWAY

LCD: 8/1/2009

PCI Family: IowaAACTWSE

Surface Type: AAC

Rank: P

Section Area (sf): 7,434.00

Length (ft): 140.00

Width (ft): 35.00

From: .

To: .

Slabs:

Section Comments:

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 11/14/2022

Inspection Comments:

PCI: 54

Total Samples: 1

Surveyed: 1

Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 54

Sample Area (SF): 7,434.00

41 ALLIGATOR CRACKING	L	6.00 SF	edge
48 LONGITUDINAL/TRANSVERSE CRACKING	H	17.00 Ft	1 FT
48 LONGITUDINAL/TRANSVERSE CRACKING	L	50.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	M	18.00 Ft	2NDY
52 RAVELING	L	7,434.00 SF	
57 WEATHERING	L	7,434.00 SF	

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 35

Branch - Section ID: TAOT - 005

Branch Name: TAXIWAY A

Use: TAXIWAY

LCD: 8/1/2009	PCI Family: IowaAACTWSE
Surface Type: AAC	
Rank: P	
Section Area (sf): 8,374.00	
Length (ft): 131.00	
Width (ft): 35.00	
From: .	
To: .	
Slabs:	Section Comments:
Slab Length (ft):	
Slab Width (ft):	
Joint Length (ft):	
Last Insp Date: 11/14/2022	Inspection Comments:
PCI: 83	
Total Samples: 2	
Surveyed: 2	

Sample Number: 01

Sample Type: R	Sample Comments:
Sample PCI: 87	
Sample Area (SF): 4,251.00	
48 LONGITUDINAL/TRANSVERSE CRACKING	L 28.00 Ft LU
56 SWELLING	L 40.00 SF
57 WEATHERING	L 4,251.00 SF

Sample Number: 02

Sample Type: R	Sample Comments:
Sample PCI: 80	
Sample Area (SF): 4,123.00	
41 ALLIGATOR CRACKING	L 2.00 SF
48 LONGITUDINAL/TRANSVERSE CRACKING	L 19.00 Ft LU
50 PATCHING	L 12.00 SF
57 WEATHERING	L 4,061.00 SF
57 WEATHERING	M 50.00 SF

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 36

Branch - Section ID: TAOT - 006

Branch Name: TAXIWAY A

Use: TAXIWAY

LCD: 6/30/1970

PCI Family: IowaAPCTWSouthern

Surface Type: APC

Rank: P

Section Area (sf): 83,942.00

Length (ft): 1,240.00

Width (ft): 50.00

From: SEE MAP

To: SEE MAP

Slabs:

Section Comments:

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 11/14/2022

Inspection Comments:

PCI: 30

Total Samples: 15

Surveyed: 5

Sample Number: 06

Sample Type: R

Sample Comments:

Sample PCI: 26

Sample Area (SF): 5,000.00

41 ALLIGATOR CRACKING	M	196.00 SF	
43 BLOCK CRACKING	L	4,804.00 SF	
47 JOINT REFLECTION CRACKING	M	350.00 Ft	FS, 2NDY
56 SWELLING	M	45.00 SF	
57 WEATHERING	L	5,000.00 SF	

Sample Number: 07

Sample Type: R

Sample Comments:

Sample PCI: 31

Sample Area (SF): 5,000.00

41 ALLIGATOR CRACKING	M	118.00 SF	
43 BLOCK CRACKING	L	3,750.00 SF	LU 10x6
47 JOINT REFLECTION CRACKING	M	300.00 Ft	FS
48 LONGITUDINAL/TRANSVERSE CRACKING	M	110.00 Ft	W
57 WEATHERING	L	5,000.00 SF	

Sample Number: 09

Sample Type: R

Sample Comments:

Sample PCI: 30

Sample Area (SF): 5,000.00

41 ALLIGATOR CRACKING	M	72.00 SF	
47 JOINT REFLECTION CRACKING	M	600.00 Ft	FS
48 LONGITUDINAL/TRANSVERSE CRACKING	L	122.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	M	240.00 Ft	W, 2NDY
56 SWELLING	L	150.00 SF	
57 WEATHERING	L	5,000.00 SF	

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 37

Sample Number: 13

Sample Type: R

Sample Comments:

Sample PCI: 33

Sample Area (SF): 5,000.00

41 ALLIGATOR CRACKING	M	66.00 SF	
43 BLOCK CRACKING	L	3,500.00 SF	
47 JOINT REFLECTION CRACKING	M	400.00 Ft	FS
48 LONGITUDINAL/TRANSVERSE CRACKING	M	126.00 Ft	
57 WEATHERING	L	5,000.00 SF	

Sample Number: 14

Sample Type: R

Sample Comments:

Sample PCI: 30

Sample Area (SF): 5,000.00

41 ALLIGATOR CRACKING	M	130.00 SF	edge
43 BLOCK CRACKING	L	1,250.00 SF	LU 6x8
47 JOINT REFLECTION CRACKING	M	375.00 Ft	FS
48 LONGITUDINAL/TRANSVERSE CRACKING	L	160.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	M	245.00 Ft	W, 2NDY
57 WEATHERING	L	5,000.00 SF	

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 38

Branch - Section ID: TAOT - 007

Branch Name: TAXIWAY A

Use: TAXIWAY

LCD: 6/3/2018

PCI Family: IowaPCCTWSE_Enhanced

Surface Type: PCC

Rank: P

Section Area (sf): 28,447.00

Length (ft): 640.00

Width (ft): 35.00

From: .

To: .

Slabs: 328

Section Comments:

Slab Length (ft): 10.00

Slab Width (ft): 8.80

Joint Length (ft): 5,300.93

Last Insp Date: 11/14/2022

Inspection Comments:

PCI: 98

Total Samples: 18

Surveyed: 7

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 06

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 08

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 10

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 25.00

65 JOINT SEAL DAMAGE

L

25.00 Slabs

Sample Number: 13

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 14

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 39

Sample Number: 16

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 15.00

65 JOINT SEAL DAMAGE

L

15.00 Slabs

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 40

Branch - Section ID: TAOT - 008

Branch Name: TAXIWAY A

Use: TAXIWAY

LCD: 6/3/2018 PCI Family: IowaPCCTWSE_Enhanced
 Surface Type: PCC
 Rank: P
 Section Area (sf): 42,805.00
 Length (ft): 1,040.00
 Width (ft): 35.00
 From: .
 To: .
 Slabs: 480 Section Comments:
 Slab Length (ft): 10.00
 Slab Width (ft): 8.80
 Joint Length (ft): 7,775.24
 Last Insp Date: 11/14/2022 Inspection Comments:
 PCI: 97
 Total Samples: 24
 Surveyed: 7

Sample Number: 02

Sample Type: R Sample Comments:
 Sample PCI: 94
 Sample Area (Slabs): 19.00
 65 JOINT SEAL DAMAGE L 19.00 Slabs
 73 SHRINKAGE CRACKING N 1.00 Slabs
 74 JOINT SPALL L 2.00 Slabs

Sample Number: 04

Sample Type: R Sample Comments:
 Sample PCI: 98
 Sample Area (Slabs): 20.00
 65 JOINT SEAL DAMAGE L 20.00 Slabs

Sample Number: 07

Sample Type: R Sample Comments:
 Sample PCI: 98
 Sample Area (Slabs): 22.00
 65 JOINT SEAL DAMAGE L 22.00 Slabs

Sample Number: 12

Sample Type: R Sample Comments:
 Sample PCI: 98
 Sample Area (Slabs): 20.00
 65 JOINT SEAL DAMAGE L 20.00 Slabs

Sample Number: 15

Sample Type: R Sample Comments:
 Sample PCI: 98
 Sample Area (Slabs): 25.00
 65 JOINT SEAL DAMAGE L 25.00 Slabs

Sample Number: 18

Sample Type: R Sample Comments:
 Sample PCI: 98
 Sample Area (Slabs): 20.00
 65 JOINT SEAL DAMAGE L 20.00 Slabs

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 41

Sample Number: 21

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 42

Branch - Section ID: TBOT - 001

Branch Name: TAXIWAY B

Use: TAXIWAY

LCD: 6/1/2006

PCI Family: IowaAPCTWSouthern

Surface Type: APC

Rank: P

Section Area (sf): 23,338.00

Length (ft): 300.00

Width (ft): 80.00

From: RUNWAY INTERSECTIONS

To: HANGAR AREA

Slabs:

Section Comments:

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 11/14/2022

Inspection Comments:

PCI: 26

Total Samples: 6

Surveyed: 4

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 26

Sample Area (SF): 4,060.00

41 ALLIGATOR CRACKING	M	130.00 SF	
43 BLOCK CRACKING	M	500.00 SF	
47 JOINT REFLECTION CRACKING	M	250.00 Ft	W, 2NDY, FS
48 LONGITUDINAL/TRANSVERSE CRACKING	L	320.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	M	250.00 Ft	W, 2NDY, FS
57 WEATHERING	L	4,060.00 SF	

Sample Number: 03

Sample Type: R

Sample Comments:

Sample PCI: 28

Sample Area (SF): 4,000.00

41 ALLIGATOR CRACKING	M	30.00 SF	
43 BLOCK CRACKING	L	250.00 SF	
43 BLOCK CRACKING	M	250.00 SF	
47 JOINT REFLECTION CRACKING	M	250.00 Ft	W, 2NDY, FS
48 LONGITUDINAL/TRANSVERSE CRACKING	H	58.00 Ft	SPALLING
48 LONGITUDINAL/TRANSVERSE CRACKING	L	230.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	M	210.00 Ft	W, 2NDY
57 WEATHERING	L	4,000.00 SF	

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 24

Sample Area (SF): 4,000.00

41 ALLIGATOR CRACKING	M	100.00 SF	
43 BLOCK CRACKING	L	1,250.00 SF	
43 BLOCK CRACKING	M	1,250.00 SF	
47 JOINT REFLECTION CRACKING	M	250.00 Ft	W, 2NDY, FS
48 LONGITUDINAL/TRANSVERSE CRACKING	M	200.00 Ft	W
57 WEATHERING	L	4,000.00 SF	

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 43

Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 26

Sample Area (SF): 4,000.00

41 ALLIGATOR CRACKING	M	80.00 SF	
43 BLOCK CRACKING	L	1,000.00 SF	LU, TYP. 7x7
43 BLOCK CRACKING	M	500.00 SF	W, 2NDY, TYP. 7x7
47 JOINT REFLECTION CRACKING	M	250.00 Ft	W, 2NDY, FS
48 LONGITUDINAL/TRANSVERSE CRACKING	L	170.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	M	215.00 Ft	W
57 WEATHERING	L	4,000.00 SF	

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 44

Branch - Section ID: TBOT - 002

Branch Name: TAXIWAY B

Use: TAXIWAY

LCD: 6/1/2004 PCI Family: IowaACTWSouthern

Surface Type: AC

Rank: P

Section Area (sf): 7,529.00

Length (ft): 125.00

Width (ft): 50.00

From: TWBOT-01

To: RW13OT-01

Slabs: Section Comments:

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 11/14/2022 Inspection Comments:

PCI: 61

Total Samples: 2

Surveyed: 2

Sample Number: 01

Sample Type: R Sample Comments:

Sample PCI: 62

Sample Area (SF): 3,240.00

48 LONGITUDINAL/TRANSVERSE CRACKING	L	43.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	M	146.00 Ft	W, FS
57 WEATHERING	L	2,640.00 SF	
57 WEATHERING	M	600.00 SF	

Sample Number: 02

Sample Type: R Sample Comments:

Sample PCI: 59

Sample Area (SF): 4,289.00

48 LONGITUDINAL/TRANSVERSE CRACKING	L	92.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	L	40.00 Ft	LS
48 LONGITUDINAL/TRANSVERSE CRACKING	M	121.00 Ft	W, FS
56 SWELLING	L	110.00 SF	
56 SWELLING	M	135.00 SF	
57 WEATHERING	L	4,289.00 SF	

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 45

Branch - Section ID: TBOT - 003

Branch Name: TAXIWAY B

Use: TAXIWAY

LCD: 8/4/2009

PCI Family: IowaACTWSouthern

Surface Type: AC

Rank: P

Section Area (sf): 27,004.00

Length (ft): 700.00

Width (ft): 35.00

From: .

To: .

Slabs:

Section Comments:

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 11/14/2022

Inspection Comments:

PCI: 100

Total Samples: 6

Surveyed: 4

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (SF): 4,375.00

NO DISTRESS

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 99

Sample Area (SF): 5,000.00

56 SWELLING

L

1.00 SF

Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (SF): 4,000.00

NO DISTRESS

Sample Number: 06

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (SF): 3,300.00

NO DISTRESS

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 46

Branch - Section ID: TBOT - 004

Branch Name: TAXIWAY B

Use: TAXIWAY

LCD: 8/4/2009

PCI Family: IowaACTWSouthern

Surface Type: AC

Rank: P

Section Area (sf): 88,287.00

Length (ft): 2,400.00

Width (ft): 35.00

From: .

To: .

Slabs:

Section Comments:

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 11/14/2022

Inspection Comments:

PCI: 99

Total Samples: 19

Surveyed: 5

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (SF): 4,375.00

NO DISTRESS

Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (SF): 4,375.00

48 LONGITUDINAL/TRANSVERSE CRACKING L 5.00 Ft LU

Sample Number: 11

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (SF): 4,375.00

NO DISTRESS

Sample Number: 14

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (SF): 4,375.00

NO DISTRESS

Sample Number: 18

Sample Type: R

Sample Comments:

Sample PCI: 96

Sample Area (SF): 4,375.00

48 LONGITUDINAL/TRANSVERSE CRACKING L 12.00 Ft LU

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 47

Branch - Section ID: TBOT - 005

Branch Name: TAXIWAY B

Use: TAXIWAY

LCD: 8/4/2009

PCI Family: IowaACTWSouthern

Surface Type: AC

Rank: P

Section Area (sf): 16,466.00

Length (ft): 332.00

Width (ft): 35.00

From: .

To: .

Slabs:

Section Comments:

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 11/14/2022

Inspection Comments:

PCI: 100

Total Samples: 3

Surveyed: 3

Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (SF): 5,345.00

NO DISTRESS

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (SF): 4,375.00

NO DISTRESS

Sample Number: 03

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (SF): 6,746.00

NO DISTRESS

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 48

Branch - Section ID: TBOT - 006

Branch Name: TAXIWAY B

Use: TAXIWAY

LCD: 6/1/2015

PCI Family: IowaAPCTWSouthern

Surface Type: APC

Rank: P

Section Area (sf): 24,230.00

Length (ft): 540.00

Width (ft): 35.00

From: RUNWAY INTERSECTIONS

To: HANGAR AREA

Slabs:

Section Comments:

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 11/14/2022

Inspection Comments:

PCI: 64

Total Samples: 4

Surveyed: 4

Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 59

Sample Area (SF): 6,090.00

41 ALLIGATOR CRACKING	M	10.00 SF	edge
45 DEPRESSION	L	90.00 SF	
48 LONGITUDINAL/TRANSVERSE CRACKING	L	521.00 Ft	LU
50 PATCHING	L	540.00 SF	
57 WEATHERING	L	5,550.00 SF	

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 58

Sample Area (SF): 6,090.00

45 DEPRESSION	L	300.00 SF	
48 LONGITUDINAL/TRANSVERSE CRACKING	L	828.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	M	50.00 Ft	FS
57 WEATHERING	L	6,090.00 SF	

Sample Number: 03

Sample Type: R

Sample Comments:

Sample PCI: 64

Sample Area (SF): 6,090.00

45 DEPRESSION	L	350.00 SF	
48 LONGITUDINAL/TRANSVERSE CRACKING	L	520.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	M	75.00 Ft	W, FS
57 WEATHERING	L	6,090.00 SF	

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 78

Sample Area (SF): 5,960.00

45 DEPRESSION	L	63.00 SF	
48 LONGITUDINAL/TRANSVERSE CRACKING	L	229.00 Ft	LU
57 WEATHERING	L	5,960.00 SF	

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 49

Branch - Section ID: TBOT - 007

Branch Name: TAXIWAY B

Use: TAXIWAY

LCD: 6/3/2018 Surface Type: PCC Rank: P Section Area (sf): 25,868.00 Length (ft): 400.00 Width (ft): 65.00 From: . To: . Slabs: 166 Slab Length (ft): 12.50 Slab Width (ft): 12.50 Joint Length (ft): 3,676.24 Last Insp Date: 11/14/2022 PCI: 96 Total Samples: 12 Surveyed: 6	PCI Family: IowaPCCTWSE_Enhanced Section Comments: Inspection Comments:
--	---

Sample Number: 02

Sample Type: R Sample PCI: 95 Sample Area (Slabs): 24.00	Sample Comments:
65 JOINT SEAL DAMAGE	L 24.00 Slabs
75 CORNER SPALL	M 1.00 Slabs

Sample Number: 03

Sample Type: R Sample PCI: 98 Sample Area (Slabs): 24.00	Sample Comments:
65 JOINT SEAL DAMAGE	L 24.00 Slabs

Sample Number: 04

Sample Type: R Sample PCI: 94 Sample Area (Slabs): 30.00	Sample Comments:
65 JOINT SEAL DAMAGE	L 30.00 Slabs
74 JOINT SPALL	M 1.00 Slabs
75 CORNER SPALL	L 1.00 Slabs

Sample Number: 06

Sample Type: R Sample PCI: 98 Sample Area (Slabs): 19.00	Sample Comments:
65 JOINT SEAL DAMAGE	L 19.00 Slabs

Sample Number: 10

Sample Type: R Sample PCI: 93 Sample Area (Slabs): 26.00	Sample Comments:
65 JOINT SEAL DAMAGE	L 26.00 Slabs
73 SHRINKAGE CRACKING	N 2.00 Slabs
75 CORNER SPALL	L 2.00 Slabs

RE-INSPECTION REPORT OTTUMWA REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: OTM

Page 50

Sample Number: 11

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 24.00

65 JOINT SEAL DAMAGE

L

24.00 Slabs

APPENDIX D

WORK HISTORY REPORT

WORK HISTORY

Pavement Database: IA 2022

Generate Date: 6/25/2023

Network ID: OTM

Page 1

Network: OTTUMWA REGIONAL AIRPORT

Branch - Section ID: A01OT - 001

LCD: 6/1/2007
 Use: APRON
 Rank: P
 Surface: AAC

Length (ft): 230.00
 Width (ft): 100.00
 True Area (sf): 20,450.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2018	PA-AD	Patching - AC Deep	\$0.00	0.00	False	EST
06-01-2010	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-01-2007	OL-AS	Overlay - AC Structural	\$0.00	0.00	True	-
06-01-1970	NC-AC	New Construction - AC	\$0.00	0.00	True	-

Branch - Section ID: A01OT - 002

LCD: 6/30/1970
 Use: APRON
 Rank: P
 Surface: APC

Length (ft): 400.00
 Width (ft): 87.00
 True Area (sf): 35,525.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2010	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-30-1970	OL-AS	Overlay - AC Structural	\$0.00	0.00	True	-
06-01-1950	NC-PC	New Construction - PCC	\$0.00	0.00	True	-

Branch - Section ID: A01OT - 003

LCD: 4/3/2021
 Use: APRON
 Rank: P
 Surface: PCC

Length (ft): 338.00
 Width (ft): 114.00
 True Area (sf): 38,700.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
04-03-2021	CR-PC	Complete Reconstruction - PCC	\$387,000.00	7.00	True	7" PCC SURFACE
04-02-2021	SB-AG	Subbase - Aggregate	\$0.00	5.00	False	5" SUBBASE - ASPHALT MILLINGS
04-01-2021	SG-CO	Subgrade - Compacted	\$0.00	12.00	False	12" SUBGRADE PREPARATION
06-01-1970	OL-AC	Overlay - AC	\$0.00	3.00	True	3" AC Overlay
06-01-1943	NC-PC	New Construction - PCC	\$0.00	8.00	True	8" PCC

Branch - Section ID: A01OT - 004

LCD: 6/1/2007
 Use: APRON
 Rank: P
 Surface: APC

Length (ft): 365.00
 Width (ft): 25.00
 True Area (sf): 12,713.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2007	OL-AS	Overlay - AC Structural	\$0.00	0.00	True	-
01-01-1970	NC-PC	New Construction - PCC	\$0.00	0.00	True	ESTIMATED CONSTRUCTION DATE

WORK HISTORY

Pavement Database: IA 2022

Generate Date: 6/25/2023

Network ID: OTM

Page 2

Branch - Section ID: A01OT - 005

LCD: 1/1/1970
 Use: APRON
 Rank: P
 Surface: APC

Length (ft): 250.00
 Width (ft): 35.00
 True Area (sf): 9,713.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
01-01-1970	OL-AC	Overlay - AC	\$0.00	0.00	True	EST
06-01-1950	NC-PC	New Construction - PCC	\$0.00	0.00	True	-

Branch - Section ID: A01OT - 006

LCD: 8/3/2018
 Use: APRON
 Rank: P
 Surface: PCC

Length (ft): 445.00
 Width (ft): 75.00
 True Area (sf): 36,044.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
08-03-2018	CR-PC	Complete Reconstruction - PCC	\$0.00	7.00	True	7" P-501
08-02-2018	SB-AG	Subbase - Aggregate	\$0.00	5.00	False	5" Modified Subbase
08-01-2018	SG-CO	Subgrade - Compacted	\$0.00	12.00	False	12" Subgrade Preparation
06-01-1970	OL-AC	Overlay - AC	\$0.00	3.00	True	3" AC Overlay
06-01-1943	NC-PC	New Construction - PCC	\$0.00	8.00	True	8" PCC

Branch - Section ID: A01OT - 007

LCD: 8/3/2019
 Use: APRON
 Rank: P
 Surface: PCC

Length (ft): 343.00
 Width (ft): 100.00
 True Area (sf): 34,176.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
08-03-2019	CR-PC	Complete Reconstruction - PCC	\$0.00	7.00	True	7" P-501
08-02-2019	SB-AG	Subbase - Aggregate	\$0.00	5.00	False	5" Modified Subbase
08-01-2019	SG-CO	Subgrade - Compacted	\$0.00	12.00	False	12" Subgrade Preparation
06-01-1970	OL-AC	Overlay - AC	\$0.00	3.00	True	3" AC Overlay
06-01-1943	NC-PC	New Construction - PCC	\$0.00	8.00	True	8" PCC

Branch - Section ID: A01OT - 008

LCD: 8/3/2016
 Use: APRON
 Rank: P
 Surface: PCC

Length (ft): 280.00
 Width (ft): 100.00
 True Area (sf): 25,031.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
08-03-2016	CR-PC	Complete Reconstruction - PCC	\$0.00	7.00	True	7" P-501
08-02-2016	SB-AG	Subbase - Aggregate	\$0.00	5.00	False	5" Modified Subbase
08-01-2016	SG-CO	Subgrade - Compacted	\$0.00	12.00	False	12" Subgrade preparation
06-01-1970	OL-AC	Overlay - AC	\$0.00	3.00	True	3" AC Overlay
06-01-1943	NC-PC	New Construction - PCC	\$0.00	8.00	True	8" PCC

WORK HISTORY

Pavement Database: IA 2022

Generate Date: 6/25/2023

Network ID: OTM

Page 3

Branch - Section ID: A01OT - 009

LCD: 4/3/2022
 Use: APRON
 Rank: P
 Surface: PCC

Length (ft): 338.00
 Width (ft): 36.00
 True Area (sf): 12,163.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
04-03-2022	CR-PC	Complete Reconstruction - PCC	\$121,630.00	7.00	True	7" PCC SURFACE
04-02-2022	SB-AG	Subbase - Aggregate	\$0.00	5.00	False	5" SUBBASE - ASPHALT MILLINGS
04-01-2022	SG-CO	Subgrade - Compacted	\$0.00	12.00	False	12" SUBGRADE PREPARATION
06-01-1970	OL-AC	Overlay - AC	\$0.00	3.00	True	3" AC Overlay
06-01-1943	NC-PC	New Construction - PCC	\$0.00	8.00	True	8" PCC

Branch - Section ID: A02OT - 001

LCD: 6/30/1970
 Use: APRON
 Rank: P
 Surface: APC

Length (ft): 700.00
 Width (ft): 75.00
 True Area (sf): 71,191.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-30-1970	OL-AS	Overlay - AC Structural	\$0.00	3.00	True	3" AC Overlay
06-01-1943	NC-PC	New Construction - PCC	\$0.00	8.00	True	8" PCC

Branch - Section ID: A02OT - 002

LCD: 8/11/2001
 Use: APRON
 Rank: P
 Surface: AC

Length (ft): 640.00
 Width (ft): 140.00
 True Area (sf): 79,574.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2015	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-01-2010	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
08-11-2001	NC-AC	New Construction - AC	\$0.00	2.00	True	2" P-401 AC
08-10-2001	BA-BI	Base Course - Bituminous	\$0.00	4.00	False	4" P-401 Bit. Base
08-09-2001	BA-AG	Base Course - Aggregate	\$0.00	9.00	False	9" P-209 Agg Base

Branch - Section ID: A02OT - 003

LCD: 2/11/1970
 Use: APRON
 Rank: P
 Surface: APC

Length (ft): 160.00
 Width (ft): 35.00
 True Area (sf): 5,600.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
02-11-1970	OL-AC	Overlay - AC	\$0.00	0.00	True	-
01-01-1960	NC-PC	New Construction - PCC	\$0.00	0.00	True	-

WORK HISTORY

Pavement Database: IA 2022

Generate Date: 6/25/2023

Network ID: OTM

Page 4

Branch - Section ID: A02OT - 004

LCD: 2/11/2012
 Use: APRON
 Rank: P
 Surface: APC

Length (ft): 90.00
 Width (ft): 35.00
 True Area (sf): 3,150.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
02-11-2012	OL-AC	Overlay - AC	\$0.00	0.00	True	EST
01-01-1960	NC-PC	New Construction - PCC	\$0.00	0.00	True	-

Branch - Section ID: R04OT - 001

LCD: 8/1/2009
 Use: RUNWAY
 Rank: S
 Surface: APC

Length (ft): 554.00
 Width (ft): 100.00
 True Area (sf): 37,912.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-02-2021	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	P-626 SLURRY SEAL
06-01-2021	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	CRACK SEAL (PRE-SLURRY SEAL)
06-01-2021	PA-AD	Patching - AC Deep	\$0.00	0.00	False	FULL DEPTH PATCH (PRE-SLURRY SEAL)
08-01-2009	OL-AS	Overlay - AC Structural	\$0.00	3.00	True	3" AC
06-30-1986	OL-AS	Overlay - AC Structural	\$0.00	2.50	True	2.5" AC
06-01-1960	NC-PC	New Construction - PCC	\$0.00	8.00	True	8" PCC

Branch - Section ID: R04OT - 002

LCD: 8/1/2009
 Use: RUNWAY
 Rank: S
 Surface: APC

Length (ft): 3,223.00
 Width (ft): 100.00
 True Area (sf): 322,356.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-02-2021	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	P-626 SLURRY SEAL
06-01-2021	PA-AD	Patching - AC Deep	\$0.00	0.00	False	FULL DEPTH PATCH (PRE-SLURRY SEAL)
06-01-2021	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	CRACK SEAL (PRE-SLURRY SEAL)
08-01-2009	OL-AS	Overlay - AC Structural	\$0.00	3.00	True	3" AC
06-30-1970	OL-AS	Overlay - AC Structural	\$0.00	2.50	True	2.5" AC
06-01-1960	NC-PC	New Construction - PCC	\$0.00	9.00	True	9" PCC

Branch - Section ID: R04OT - 003

LCD: 8/4/2009
 Use: RUNWAY
 Rank: S
 Surface: AC

Length (ft): 498.00
 Width (ft): 100.00
 True Area (sf): 49,829.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-02-2021	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	P-626 SLURRY SEAL
06-01-2021	PA-AD	Patching - AC Deep	\$0.00	0.00	False	FULL DEPTH PATCH (PRE-SLURRY SEAL)
06-01-2021	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	CRACK SEAL (PRE-SLURRY SEAL)
08-04-2009	NC-AC	New Construction - AC	\$0.00	4.00	True	4" P-401
08-03-2009	BA-AG	Base Course - Aggregate	\$0.00	12.00	False	12" P-209
08-02-2009	SB-AG	Subbase - Aggregate	\$0.00	4.00	False	RECLAIMED MATERIAL
08-01-2009	SG-CO	Subgrade - Compacted	\$0.00	9.00	False	-

WORK HISTORY

Pavement Database: IA 2022

Generate Date: 6/25/2023

Network ID: OTM

Page 5

Branch - Section ID: R04OT - 004

LCD: 6/3/2018
 Use: RUNWAY
 Rank: S
 Surface: PCC

Length (ft): 400.00
 Width (ft): 100.00
 True Area (sf): 40,000.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-03-2018	CR-PC	Complete Reconstruction - PCC	\$0.00	6.00	True	6" P-501
06-02-2018	BA-AG	Base Course - Aggregate	\$0.00	4.00	False	4" P-209
06-01-2018	SG-ST	Subgrade - Stabilized	\$0.00	12.00	False	12" P-158 Fly Ash Treated Subgrade
08-01-2009	OL-AS	Overlay - AC Structural	\$0.00	3.00	True	3" AC
06-30-1986	OL-AS	Overlay - AC Structural	\$0.00	2.50	True	2.5" AC
06-01-1960	NC-PC	New Construction - PCC	\$0.00	8.00	True	8" PCC

Branch - Section ID: R13OT - 001

LCD: 6/3/2018
 Use: RUNWAY
 Rank: P
 Surface: PCC

Length (ft): 6,007.00
 Width (ft): 100.00
 True Area (sf): 601,045.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-03-2018	CR-PC	Complete Reconstruction - PCC	\$0.00	8.50	True	8.5" P-501
06-02-2018	BA-AG	Base Course - Aggregate	\$0.00	8.00	False	8" P-209
06-01-2018	SG-ST	Subgrade - Stabilized	\$0.00	12.00	False	12" P-158 Fly Ash Treated Subgrade
06-01-2011	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-01-2011	PA-AD	Patching - AC Deep	\$0.00	0.00	False	-
04-04-1993	OL-AC	Overlay - AC	\$0.00	0.00	True	EST
06-01-1964	NC-AC	New Construction - AC	\$0.00	3.00	True	-

Branch - Section ID: TAOT - 001

LCD: 6/1/2004
 Use: TAXIWAY
 Rank: P
 Surface: AC

Length (ft): 1,680.00
 Width (ft): 35.00
 True Area (sf): 59,790.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2010	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-01-2004	CR-AC	Complete Reconstruction - AC	\$0.00	0.00	True	-
06-30-1970	NC-AC	New Construction - AC	\$0.00	0.00	True	-

Branch - Section ID: TAOT - 002

LCD: 5/1/2004
 Use: TAXIWAY
 Rank: P
 Surface: AC

Length (ft): 145.00
 Width (ft): 35.00
 True Area (sf): 6,507.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
05-01-2004	NC-AC	New Construction - AC	\$0.00	0.00	True	-

WORK HISTORY

Pavement Database: IA 2022

Generate Date: 6/25/2023

Network ID: OTM

Page 6

Branch - Section ID: TAOT - 003

LCD: 8/4/2002
 Use: TAXIWAY
 Rank: P
 Surface: AC

Length (ft): 1,977.00
 Width (ft): 35.00
 True Area (sf): 68,546.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
08-04-2002	NC-AC	New Construction - AC	\$0.00	2.00	True	2" P-401 AC
08-03-2002	BA-BI	Base Course - Bituminous	\$0.00	4.00	False	4" P-401 Asphalt Base
08-02-2002	BA-AG	Base Course - Aggregate	\$0.00	9.00	False	9" P-209 Agg Base
08-01-2002	SG-CO	Subgrade - Compacted	\$0.00	0.00	False	P-152 Compacted SG

Branch - Section ID: TAOT - 004

LCD: 8/1/2009
 Use: TAXIWAY
 Rank: P
 Surface: AAC

Length (ft): 140.00
 Width (ft): 35.00
 True Area (sf): 7,434.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
08-01-2009	OL-AS	Overlay - AC Structural	\$0.00	3.00	True	-
05-01-2004	NC-AC	New Construction - AC	\$0.00	0.00	True	-

Branch - Section ID: TAOT - 005

LCD: 8/1/2009
 Use: TAXIWAY
 Rank: P
 Surface: AAC

Length (ft): 131.00
 Width (ft): 35.00
 True Area (sf): 8,374.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
08-01-2009	OL-AS	Overlay - AC Structural	\$0.00	3.00	True	-
05-01-2004	NC-AC	New Construction - AC	\$0.00	0.00	True	-

Branch - Section ID: TAOT - 006

LCD: 6/30/1970
 Use: TAXIWAY
 Rank: P
 Surface: APC

Length (ft): 1,240.00
 Width (ft): 50.00
 True Area (sf): 83,942.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2010	CS-AC	Crack Sealing - AC	\$0.00	0.00	False	-
06-30-1970	OL-AS	Overlay - AC Structural	\$0.00	0.00	True	-
06-01-1960	NC-PC	New Construction - PCC	\$0.00	0.00	True	-

WORK HISTORY

Pavement Database: IA 2022

Generate Date: 6/25/2023

Network ID: OTM

Page 7

Branch - Section ID: TAOT - 007

LCD: 6/3/2018
 Use: TAXIWAY
 Rank: P
 Surface: PCC

Length (ft): 640.00
 Width (ft): 35.00
 True Area (sf): 28,447.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-03-2018	CR-PC	Complete Reconstruction - PCC	\$0.00	8.50	True	8.5" P-501
06-02-2018	BA-AG	Base Course - Aggregate	\$0.00	8.00	False	8" P-209
06-01-2018	SG-ST	Subgrade - Stabilized	\$0.00	12.00	False	12" P-158 Fly Ash Treated Subgrade
08-04-2002	NC-AC	New Construction - AC	\$0.00	2.00	True	2" P-401 AC
08-03-2002	BA-BI	Base Course - Bituminous	\$0.00	4.00	False	4" P-401 Asphalt Base
08-02-2002	BA-AG	Base Course - Aggregate	\$0.00	9.00	False	9" P-209 Agg Base
08-01-2002	SG-CO	Subgrade - Compacted	\$0.00	0.00	False	P-152 Compacted SG

Branch - Section ID: TAOT - 008

LCD: 6/3/2018
 Use: TAXIWAY
 Rank: P
 Surface: PCC

Length (ft): 1,040.00
 Width (ft): 35.00
 True Area (sf): 42,805.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-03-2018	CR-PC	Complete Reconstruction - PCC	\$0.00	8.50	True	8.5" P-501
06-02-2018	BA-AG	Base Course - Aggregate	\$0.00	8.00	False	8" P-209
06-01-2018	SG-ST	Subgrade - Stabilized	\$0.00	12.00	False	12" P-158 Fly Ash Treated Subgrade
06-01-2004	CR-AC	Complete Reconstruction - AC	\$0.00	0.00	True	-
06-30-1970	NC-AC	New Construction - AC	\$0.00	0.00	True	-

Branch - Section ID: TBOT - 001

LCD: 6/1/2006
 Use: TAXIWAY
 Rank: P
 Surface: APC

Length (ft): 300.00
 Width (ft): 80.00
 True Area (sf): 23,338.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2006	OL-AS	Overlay - AC Structural	\$0.00	0.00	True	-
06-30-1970	OL-AS	Overlay - AC Structural	\$0.00	0.00	True	-
06-01-1960	NC-PC	New Construction - PCC	\$0.00	0.00	True	-

Branch - Section ID: TBOT - 002

LCD: 6/1/2004
 Use: TAXIWAY
 Rank: P
 Surface: AC

Length (ft): 125.00
 Width (ft): 50.00
 True Area (sf): 7,529.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2004	NC-AC	New Construction - AC	\$0.00	0.00	True	-

WORK HISTORY

Pavement Database: IA 2022

Generate Date: 6/25/2023

Network ID: OTM

Page 8

Branch - Section ID: TBOT - 003

LCD: 8/4/2009
 Use: TAXIWAY
 Rank: P
 Surface: AC

Length (ft): 700.00
 Width (ft): 35.00
 True Area (sf): 27,004.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-02-2021	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	P-626 SLURRY SEAL
08-04-2009	NC-AC	New Construction - AC	\$0.00	4.00	True	4" P-401 AC
08-03-2009	BA-AG	Base Course - Aggregate	\$0.00	12.00	False	12" P-209
08-02-2009	BA-AG	Base Course - Aggregate	\$0.00	4.00	False	RECLAIMED AC
08-01-2009	SB-AG	Subbase - Aggregate	\$0.00	9.00	False	-

Branch - Section ID: TBOT - 004

LCD: 8/4/2009
 Use: TAXIWAY
 Rank: P
 Surface: AC

Length (ft): 2,400.00
 Width (ft): 35.00
 True Area (sf): 88,287.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-02-2021	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	P-626 SLURRY SEAL
08-04-2009	NC-AC	New Construction - AC	\$0.00	4.00	True	-
08-03-2009	BA-AG	Base Course - Aggregate	\$0.00	12.00	False	-
08-02-2009	BA-AG	Base Course - Aggregate	\$0.00	4.00	False	RECLAIMED AC
08-01-2009	SB-AG	Subbase - Aggregate	\$0.00	9.00	False	-

Branch - Section ID: TBOT - 005

LCD: 8/4/2009
 Use: TAXIWAY
 Rank: P
 Surface: AC

Length (ft): 332.00
 Width (ft): 35.00
 True Area (sf): 16,466.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-02-2021	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	P-626 SLURRY SEAL
08-04-2009	NC-AC	New Construction - AC	\$0.00	4.00	True	-
08-03-2009	BA-AG	Base Course - Aggregate	\$0.00	12.00	False	-
08-02-2009	BA-AG	Base Course - Aggregate	\$0.00	4.00	False	RECLAIMED AC
08-01-2009	SB-AG	Subbase - Aggregate	\$0.00	9.00	False	-

Branch - Section ID: TBOT - 006

LCD: 6/1/2015
 Use: TAXIWAY
 Rank: P
 Surface: APC

Length (ft): 540.00
 Width (ft): 35.00
 True Area (sf): 24,230.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2021	PA-AD	Patching - AC Deep	\$0.00	0.00	False	ESTIMATE
06-01-2015	OL-AC	Overlay - AC	\$101,515.00	2.50	True	2.5"-3" MILL/2.5"-3" OVERLAY
06-01-1970	OL-AC	Overlay - AC	\$0.00	3.00	True	3" AC OV
07-13-1943	NC-PC	New Construction - PCC	\$0.00	8.00	True	8" PCC

WORK HISTORY

Pavement Database: IA 2022

Generate Date: 6/25/2023

Network ID: OTM

Page 9

Branch - Section ID: TBOT - 007

LCD: 6/3/2018
Use: TAXIWAY
Rank: P
Surface: PCC

Length (ft): 400.00
Width (ft): 65.00
True Area (sf): 25,868.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-03-2018	CR-PC	Complete Reconstruction - PCC	\$0.00	6.00	True	6" P-501
06-02-2018	BA-AG	Base Course - Aggregate	\$0.00	4.00	False	4" P-209
06-01-2018	SG-ST	Subgrade - Stabilized	\$0.00	12.00	False	12" P-158 Fly Ash Treated Subgrade
06-01-2004	NC-AC	New Construction - AC	\$0.00	0.00	True	-

APPENDIX E

LOCALIZED PREVENTIVE MAINTENANCE POLICIES AND UNIT COST TABLES

Table E-1. Localized preventive maintenance policy, asphalt-surfaced pavements.

Distress Type	Severity Level	Maintenance Action
Alligator Cracking	Low	Monitor
Alligator Cracking	Medium	Asphalt Patch
Alligator Cracking	High	Asphalt Patch
Bleeding	N/A	Monitor
Block Cracking	Low	Monitor
Block Cracking	Medium	Crack Seal—Asphalt
Block Cracking	High	Crack Seal—Asphalt
Corrugation	Low	Monitor
Corrugation	Medium	Asphalt Patch
Corrugation	High	Asphalt Patch
Depression	Low	Monitor
Depression	Medium	Monitor
Depression	High	Asphalt Patch
Jet-Blast Erosion	N/A	Asphalt Patch
Joint Reflection Cracking	Low	Monitor
Joint Reflection Cracking	Medium	Crack Seal—Asphalt
Joint Reflection Cracking	High	Crack Seal—Asphalt
L&T Cracking	Low	Monitor
L&T Cracking	Medium	Crack Seal—Asphalt
L&T Cracking	High	Crack Seal—Asphalt
Oil Spillage	N/A	Asphalt Patch
Patching	Low	Monitor
Patching	Medium	Asphalt Patch
Patching	High	Asphalt Patch
Polished Aggregate	N/A	Monitor
Raveling	Low	Monitor
Raveling	Medium	Asphalt Patch
Raveling	High	Asphalt Patch
Rutting	Low	Monitor
Rutting	Medium	Monitor
Rutting	High	Asphalt Patch
Shoving	Low	Monitor
Shoving	Medium	Asphalt Patch
Shoving	High	Asphalt Patch
Slippage Cracking	N/A	Asphalt Patch
Swelling	Low	Monitor
Swelling	Medium	Monitor
Swelling	High	Asphalt Patch
Weathering	Low	Monitor
Weathering	Medium	Monitor
Weathering	High	Asphalt Patch

Table E-2. Localized preventive maintenance policy, PCC pavements.

Distress Type	Severity Level	Maintenance Action
ASR	Low	Monitor
ASR	Medium	Slab Replacement
ASR	High	Slab Replacement
Blowup	Low	Slab Replacement
Blowup	Medium	Slab Replacement
Blowup	High	Slab Replacement
Corner Break	Low	Crack Seal—PCC
Corner Break	Medium	Full Depth PCC Patch
Corner Break	High	Full Depth PCC Patch
Durability Cracking	Low	Monitor
Durability Cracking	Medium	Full Depth Patch
Durability Cracking	High	Slab Replacement
Faulting	Low	Monitor
Faulting	Medium	Grinding
Faulting	High	Slab Replacement
Joint Seal Damage	Low	Monitor
Joint Seal Damage	Medium	Joint Seal
Joint Seal Damage	High	Joint Seal
LTD Cracking	Low	Monitor
LTD Cracking	Medium	Crack Seal—PCC
LTD Cracking	High	Slab Replacement
Patching (Small and Large)	Low	Monitor
Patching (Small and Large)	Medium	Full Depth PCC Patch
Patching (Small and Large)	High	Full Depth PCC Patch
Popouts	N/A	Monitor
Pumping	N/A	Monitor
Scaling	Low	Monitor
Scaling	Medium	Partial Depth PCC Patch
Scaling	High	Slab Replacement
Shattered Slab	Low	Crack Seal—PCC
Shattered Slab	Medium	Slab Replacement
Shattered Slab	High	Slab Replacement
Shrinkage Cracking	N/A	Monitor
Spalling (Joint and Corner)	Low	Monitor
Spalling (Joint and Corner)	Medium	Partial Depth PCC Patch
Spalling (Joint and Corner)	High	Partial Depth PCC Patch

Table E-3. 2023 unit costs for localized preventive maintenance actions.

Maintenance Action	Unit Cost
Asphalt Patch—Asphalt-Surfaced Pavement	\$15.24/sf
Crack Sealing—Asphalt-Surfaced Pavement	\$2.61/lf
Partial Depth PCC Patch—PCC Pavement	\$39.04/sf
Full Depth PCC Patch—PCC Pavement	\$17.43/sf
Crack Sealing—PCC Pavement	\$3.14/lf
Joint Sealing—PCC Pavement	\$3.14/lf
Grinding—PCC Pavement	\$0.37/sf
Slab Replacement—PCC Pavement	\$17.43/sf

Table Note: The unit cost estimates are based on broad statewide numbers and should be adjusted to reflect local costs.

Table E-4. 2023 unit costs (per square foot) based on pavement type and PCI ranges.

Pavement Type	PCI Range 0–40	PCI Range 40–50	PCI Range 50–60	PCI Range 60–70	PCI Range 70–80	PCI Range 80–90	PCI Range 90–100
AC	\$10.82	\$5.12	\$5.12	\$5.12	\$0.00	\$0.00	\$0.00
PCC	\$18.08	\$8.55	\$8.55	\$8.55	\$0.00	\$0.00	\$0.00

Table Note: The unit cost estimates are based on broad statewide numbers and should be adjusted to reflect local costs.

APPENDIX F

YEAR 2023 LOCALIZED PREVENTIVE MAINTENANCE DETAILS

Table F-1. Year 2023 localized preventive maintenance details.

Branch	Section	Distress Type	Severity	Distress Quantity	Distress Unit	Maintenance Action	Unit Cost	2023 Estimated Cost
A01OT	03	Joint Spalling	Medium	3	Slabs	Patching - PCC Partial Depth	\$39.04	\$697
A01OT	06	Blow-up	Low	3	Slabs	Slab Replacement - PCC	\$17.43	\$5,653
A01OT	06	Corner Spalling	Medium	3	Slabs	Patching - PCC Partial Depth	\$39.04	\$273
A01OT	06	Joint Seal Damage	Medium	47	Slabs	Joint Seal (Localized)	\$3.14	\$3,018
A01OT	07	Joint Spalling	Medium	2	Slabs	Patching - PCC Partial Depth	\$39.04	\$553
A01OT	08	Corner Break	Low	7	Slabs	Crack Sealing - PCC	\$3.14	\$167
A01OT	08	Corner Spalling	Medium	1	Slabs	Patching - PCC Partial Depth	\$39.04	\$105
A01OT	08	Joint Seal Damage	Medium	43	Slabs	Joint Seal (Localized)	\$3.14	\$2,537
A01OT	08	Joint Spalling	Medium	1	Slabs	Patching - PCC Partial Depth	\$39.04	\$252
R13OT	01	Joint Spalling	Medium	10	Slabs	Patching - PCC Partial Depth	\$39.04	\$2,425
TAOT	01	L&T Cracking	Medium	1,380	Ft	Crack Sealing - AC	\$2.61	\$3,601
TAOT	01	Raveling	Medium	5	SqFt	Patching - AC Deep	\$15.24	\$79
TBOT	07	Corner Spalling	Medium	1	Slabs	Patching - PCC Partial Depth	\$39.04	\$119
TBOT	07	Joint Spalling	Medium	1	Slabs	Patching - PCC Partial Depth	\$39.04	\$285

Table Notes:

1. See Figure 3 for the location of the branch and section.
2. Distress types are defined by ASTM D5340-20. L&T Cracking = Longitudinal and Transverse Cracking; LTD Cracking = Longitudinal, Transverse, and Diagonal Cracking; ASR = Alkali-Silica Reaction.
3. The costs provided are of a general nature for the entire state and may require adjustment to reflect specific conditions at Ottumwa Regional Airport.



PREPARED FOR

Iowa Department of Transportation
Modal Transportation Bureau
800 Lincoln Way
Ames, Iowa 50010
515-239-1691
<https://iowadot.gov/aviation>

JULY 2023