

# Spirit Lake Municipal Airport

**PAVEMENT MANAGEMENT REPORT**



**PREPARED BY**

Applied Pavement Technology, Inc.  
115 West Main Street, Suite 400  
Urbana, Illinois 61801  
(217) 398-3977  
[www.appliedpavement.com](http://www.appliedpavement.com)

**AUGUST 2019**



# **SPIRIT LAKE MUNICIPAL AIRPORT PAVEMENT MANAGEMENT REPORT**

*PREPARED FOR:*

**IOWA DEPARTMENT OF TRANSPORTATION  
AVIATION BUREAU**

*PREPARED BY:*

**APPLIED PAVEMENT TECHNOLOGY, INC.**

*IN ASSOCIATION WITH:*

**ROBINSON ENGINEERING COMPANY**

August 2019

The preparation of this document was financed in part through an Airport Improvement Program grant from the Federal Aviation Administration (Project Number 3-19-0000-024-2018) as provided under Section 505 of the Airport and Airway Improvement Act of 1982, as amended. The contents do not necessarily reflect the DOT's official views or the policy of the FAA. Acceptance of this report by the FAA does not in any way constitute a commitment on the part of the United States to participate in any development depicted therein nor does it indicate the proposed development is environmentally acceptable in accordance with appropriate public laws.

## TABLE OF CONTENTS

|   |    |
|---|----|
| INTRODUCTION .....  | 1  |
| PAVEMENT INVENTORY .....                                      | 2  |
| PAVEMENT EVALUATION.....                                      | 4  |
| Pavement Evaluation Procedure .....                           | 4  |
| Pavement Evaluation Results.....                              | 5  |
| Inspection Comments.....                                      | 9  |
| Runway .....  | 9  |
| Taxiways.....   | 9  |
| Apron .....   | 9  |
| PAVEMENT MAINTENANCE AND REHABILITATION PROGRAM .....         | 10 |
| Analysis Parameters.....                                      | 10 |
| Critical PCIs.....  | 10 |
| Localized Preventive Maintenance Policies and Unit Costs..... | 10 |
| Major Rehabilitation Unit Costs .....                         | 10 |
| Budget and Inflation Rate .....                               | 10 |
| Analysis Approach.....  | 10 |
| Analysis Results.....   | 11 |
| General Maintenance Recommendations .....                     | 11 |
| SUMMARY .....   | 13 |

## LIST OF FIGURES

|  |   |
|--|---|
| Figure 1. Pavement condition versus cost of repair.....                        | 1 |
| Figure 2. Pavement area by branch use. ....                                    | 2 |
| Figure 3. Spirit Lake Municipal Airport network definition map. ....           | 3 |
| Figure 4. Visual representation of PCI scale on typical pavement surfaces..... | 4 |
| Figure 5. PCI versus repair type. ....   | 5 |
| Figure 6. Pavement area by PCI range at Spirit Lake Municipal Airport.....     | 6 |
| Figure 7. PCI by branch use at Spirit Lake Municipal Airport.....              | 6 |
| Figure 8. Spirit Lake Municipal Airport PCI map.....                           | 7 |

## LIST OF TABLES

|  |    |
|--|----|
| Table 1. 2018 pavement evaluation results.....                                 | 8  |
| Table 2. 5-year M&R program under an unlimited funding analysis scenario. .... | 11 |

## APPENDIXES

|  |     |
|--|-----|
| Appendix A. Cause of Distress Tables .....                                       | A-1 |
| Appendix B. Inspection Photographs .....   | B-1 |
| Appendix C. Inspection Report.....   | C-1 |
| Appendix D. Work History Report.....   | D-1 |
| Appendix E. Localized Preventive Maintenance Policies and Unit Cost Tables ..... | E-1 |
| Appendix F. Year 2019 Localized Preventive Maintenance Details.....              | F-1 |


## INTRODUCTION

Applied Pavement Technology, Inc. (APTech), with assistance from Robinson Engineering Company, updated the Airport Pavement Management System (APMS) for the Iowa Department of Transportation, Aviation Bureau (Iowa DOT). The APMS provides a means to monitor the condition of the pavements within the state of Iowa and to proactively plan for their preservation.

As part of this project, pavement conditions at Spirit Lake Municipal Airport were assessed in November 2018 using the Pavement Condition Index (PCI) procedure. During a PCI inspection, the types, severities, and amounts of distress present in a pavement are quantified. This information is then used to develop a composite index that represents the overall condition of the pavement in numerical terms, ranging from 0 (failed) to 100 (excellent). The PCI provides an overall measure of condition and an indication of the level of work that will be required to maintain or repair a pavement. The distress information also provides insight into what is causing the pavement to deteriorate, which is the first step in selecting the appropriate repair action to correct the problem.

Programmed into an APMS, PCI information is used to determine when preventive maintenance actions (such as crack or joint sealing) are advisable and to identify the most cost-effective time to perform major rehabilitation (such as an overlay or whitetopping). The importance of identifying not only the type of repair but also the optimal time of repair is illustrated in Figure 1. This figure shows that there is a point in a pavement's life cycle where the rate of deterioration increases. The financial impact of delaying repairs beyond this point can be severe.

Figure 1. Pavement condition versus cost of repair.



The pavement evaluation results for Spirit Lake Municipal Airport are presented within this report and can be used by the Iowa DOT, the Federal Aviation Administration (FAA), and Spirit Lake Municipal Airport to identify, prioritize, and schedule pavement maintenance and rehabilitation (M&R) actions at the airport. In addition to this report, the web-based Interactive Data Exchange Application (IDEA) containing the pavement management information collected during this project was updated and may be accessed from the Iowa DOT's website.

## PAVEMENT INVENTORY


The pavement network at Spirit Lake Municipal Airport was divided into branches, sections, and sample units for pavement management purposes. A branch is a single entity that serves a distinct function. For example, a runway is considered a branch because it serves a single function (allowing aircraft to take off and land). Taxiways, and aprons are also separate branches.

Each branch was further divided into sections. Traditionally, sections are defined as parts of the branch that share common attributes, such as cross-section, last construction date, traffic level, and performance. Using this approach, if a runway was built in 1968 and then extended in 1984, it would contain two separate sections.

To estimate the overall condition of a pavement section, each section was subdivided into sample units. Portions of these sample units were evaluated during the pavement inspection, and the collected information was extrapolated to predict the condition of the section as a whole.

Approximately 184,748 square feet of pavement were evaluated at Spirit Lake Municipal Airport, as illustrated in Figure 2. This figure also shows the area-weighted age in years of the pavements at the time of the inspection. Figure 3 provides a map that details how the pavement network was divided into management units and identifies the sample units that were evaluated during the pavement inspection at Spirit Lake Municipal Airport.

Figure 2. Pavement area by branch use.





## PAVEMENT EVALUATION

### Pavement Evaluation Procedure

APTech inspected the pavements at Spirit Lake Municipal Airport using the PCI procedure described in:

- FAA Advisory Circular 150/5380-6C, *Guidelines and Procedures for Maintenance of Airport Pavements* ([https://www.faa.gov/documentLibrary/media/Advisory\\_Circular/150-5380-6C.pdf](https://www.faa.gov/documentLibrary/media/Advisory_Circular/150-5380-6C.pdf)).
- FAA Advisory Circular 150/5380-7B, *Airport Pavement Management Program (PMP)* ([https://www.faa.gov/documentLibrary/media/Advisory\\_Circular/150-5380-7B.pdf](https://www.faa.gov/documentLibrary/media/Advisory_Circular/150-5380-7B.pdf)).
- ASTM D5340-12, *Standard Test Method for Airport Pavement Condition Index Surveys*.

The PCI provides a numerical indication of overall pavement condition, as illustrated in Figure 4. The types and amounts of deterioration are used to calculate the PCI of the section. The PCI ranges from a value of 0 (representing a pavement in a failed condition) to a value of 100 (representing a pavement in excellent condition).

Figure 4. Visual representation of PCI scale on typical pavement surfaces<sup>1</sup>.



<sup>1</sup>Photographs shown are not specific to Spirit Lake Municipal Airport.

Generally, pavements with relatively high PCIs that are not exhibiting significant load-related distress will benefit from preventive maintenance actions, such as crack sealing or joint resealing. As the PCI drops, the pavements may require major rehabilitation, such as an overlay or whitetopping. In some situations where the PCI has dropped low enough, reconstruction may be the only viable alternative due to the substantial damage to the pavement structure. Figure 5 illustrates how the appropriate repair type varies with the PCI of a pavement section and provides the corresponding colors used for the maps and charts in this report for each range of PCIs.



Figure 5. PCI versus repair type.

| PCI Range | Repair                 |
|-----------|------------------------|
| 86-100    | Preventive Maintenance |
| 71-85     |                        |
| 56-70     |                        |
| 41-55     | Major Rehabilitation   |
| 26-40     | Reconstruction         |
| 11-25     |                        |
| 0-10      |                        |

The types of distress identified during the PCI inspection provide insight into the cause of pavement deterioration. PCI distress types are characterized as load-related (such as alligator cracking on asphalt-surfaced pavements or shattered slabs on portland cement concrete [PCC] pavements), climate/durability-related (such as weathering [a climate-related distress type on asphalt-surfaced pavements] and durability cracking [a durability-related distress type on PCC pavements]), and other (distress types that cannot be attributed solely to load or climate/durability). Understanding the cause of distress helps in selecting a rehabilitation alternative that corrects the cause and thus eliminates its recurrence.

Appendix A identifies the distress types considered during a PCI inspection and describes the likely cause of each distress type. It should be noted that a PCI is based on visual signs of pavement deterioration and does not provide a measure of structural capacity.

**Pavement Evaluation Results**

The pavements at Spirit Lake Municipal Airport were inspected on November 29, 2018. The 2018 area-weighted condition of Spirit Lake Municipal Airport is 34, with conditions ranging from 28 to 100 (on a scale of 0 [failed] to 100 [excellent]). During the previous pavement inspection in 2014, the area-weighted PCI of the airport was 80.

Figure 6 summarizes the overall condition of the pavements at Spirit Lake Municipal Airport, and Figure 7 presents area-weighted condition (average PCI adjusted to account for the relative size of the pavement sections) by branch use. Figure 8 is a map that displays the condition of the evaluated pavements. Table 1 summarizes the results of the pavement evaluation. Appendix B presents photographs taken during the PCI inspection, and Appendix C contains detailed information on the distresses observed during the visual survey. Appendix D includes detailed work history information that was collected during the record review process.

Figure 6. Pavement area by PCI range at Spirit Lake Municipal Airport.




Figure 7. PCI by branch use at Spirit Lake Municipal Airport.

(Values on chart are area-weighted)





FIGURE 8. PCI MAP.



**LEGEND**

|  |                    |
|--|--------------------|
|  | BRANCH IDENTIFIER  |
|  | SECTION IDENTIFIER |
|  | PCI VALUE          |
|  | SECTION BREAK LINE |

**PAVEMENT CONDITION INDEX**

| PCI    |
|--------|
| 86-100 |
| 71-85  |
| 56-70  |
| 41-55  |
| 26-40  |
| 11-25  |
| 0-10   |

|   |                                  |   |                            |
|---|----------------------------------|---|----------------------------|
|   |                                  | 115 W. Main Street, Suite 400<br>Urbana, IL 61801<br>Tel: (217) 398-3977<br>Fax: (217) 398-4027 |                            |
|   |                                  | 322 1st Street East<br>Independence, IA 50644<br>Tel: (319) 334-7211                            |                            |
| AGENCY: Iowa Department of Transportation<br>Office of Aviation |                                  |   |                            |
| LOCATION: Spirit Lake Municipal Airport<br>Spirit Lake, Iowa    |                                  |   |                            |
| PAGE TITLE: 2018 Pavement Condition Index Map                   |                                  |   |                            |
| PROJECT DATE:<br>OCT. 2018                                      | CREATION DATE:<br>OCT. 2018      | PROJECT MANAGER:<br>LJR   | JOB NUMBER:<br>17-020-AM02 |
| DRAWING SCALE:<br>1"=300'                                       | LAST MODIFIED DATE:<br>APR. 2019 | REVISED BY:<br>DSP  | DRAWN BY:<br>DSP           |
| FILENAME:<br>Spirit Lake.dwg                                    | LAYOUT NAME/NUMBER:<br>PCI       | PAGE NUMBER:<br>7   |                            |

Table 1. 2018 pavement evaluation results.

| Branch <sup>1</sup> | Section <sup>1</sup> | Surface Type <sup>2</sup> | Section Area (sf) | LCD <sup>3</sup> | 2018 PCI | % Distress due to Load <sup>4</sup> | % Distress due to Climate/Durability <sup>5</sup> | % Distress due to Other <sup>6</sup> | Type of Distresses <sup>7</sup>  |
|---------------------|----------------------|---------------------------|-------------------|------------------|----------|-------------------------------------|---|--------------------------------------|--|
| A015I               | 01                   | AAC                       | 17,520            | 1/1/2011         | 28       | 81                                  | 19  | 0                                    | Alligator Cracking, L&T Cracking, Weathering                           |
| R165I               | 01                   | AAC                       | 153,672           | 1/1/2010         | 32       | 53                                  | 47  | 0                                    | Alligator Cracking, L&T Cracking, Raveling, Weathering                 |
| T015I               | 01                   | AAC                       | 8,858             | 1/1/2011         | 56       | 32                                  | 68  | 0                                    | Alligator Cracking, Block Cracking, L&T Cracking, Raveling, Weathering |
| T025I               | 01                   | AC                        | 4,698             | 1/1/2018         | 100      | 0                                   | 0   | 0                                    | No Distress  |

<sup>1</sup>See Figure 3 for the location of the branch and section.

<sup>2</sup>AC = asphalt cement concrete; AAC = asphalt overlay on AC; PCC = portland cement concrete; APC = asphalt overlay on PCC.

<sup>3</sup>LCD = last construction date.

<sup>4</sup>Distress due to load includes those distresses attributed to a structural deficiency in the pavement, such as alligator cracking or rutting on asphalt-surfaced pavements or shattered slabs on a PCC pavement.

<sup>5</sup>Distress due to climate or durability includes those distresses attributed to either the aging of the pavement and the effects of the environment (such as weathering, raveling, or block cracking in asphalt-surfaced pavements) or to a materials-related problem (such as durability cracking or alkali-silica reaction [ASR] in a PCC pavement). If materials-related distresses were recorded during the inspection, further laboratory testing is required to definitively determine the type present.

<sup>6</sup>Other refers to distresses not attributed to one factor but rather may be caused by a combination of factors.

<sup>7</sup>Distress types are defined by ASTM D5340-12. L&T Cracking = Longitudinal and Transverse Cracking; LTD Cracking = Longitudinal, Transverse, and Diagonal Cracking; ASR = Alkali-Silica Reaction.

## Inspection Comments

Spirit Lake Municipal Airport was inspected on November 29, 2018. There were four pavement sections defined during the inspection.

### *Runway*

Runway 16/34 consisted of one section that was in poor condition. Medium-severity alligator cracking, low- and medium-severity longitudinal and transverse (L&T) cracking, and low-severity raveling and weathering were recorded throughout Section 01. The low-severity L&T cracking was sealed, and the medium-severity L&T cracking was due to either the development of secondary cracking, unsealed crack widths greater than 1/4 in, or crack sealant that was no longer performing satisfactorily.

### *Taxiways*

Taxiway 01 was defined by one section that connected the apron area with the Runway 34 approach. Medium-severity alligator cracking, low-severity block cracking, low- and medium-severity L&T cracking, and low-severity raveling and weathering were observed in Section 01. The low-severity cracking was sealed, while the medium-severity cracking was due to crack sealant that had failed.

Taxiway 02 contained one, recently constructed section that was in excellent condition. No pavement distresses were identified during the inspection.

### *Apron*

The apron area consisted of one section in poor condition. Medium-severity alligator cracking, low- and medium-severity weathering, and low-severity, sealed L&T cracking were recorded throughout Section 01.

## PAVEMENT MAINTENANCE AND REHABILITATION PROGRAM

Using the information collected during the pavement inspection, the PAVER pavement management software was used to develop a 5-year M&R program for Spirit Lake Municipal Airport. In addition, a 1-year plan for localized preventive maintenance (such as crack sealing and patching) was prepared.

### Analysis Parameters

#### *Critical PCIs*

PAVER uses critical PCIs to determine whether localized preventive maintenance or major rehabilitation is the appropriate repair action. Above the critical PCI, localized preventive maintenance activities are recommended. Below the critical PCI, major rehabilitation actions, such as an overlay or reconstruction, are recommended. The Iowa DOT set the critical PCIs at 65 for runways, 60 for taxiways, and 55 for aprons.

#### *Localized Preventive Maintenance Policies and Unit Costs*

Localized preventive maintenance policies were developed for asphalt-surfaced and PCC pavements. These policies, shown in Appendix E, identify the localized preventive maintenance actions that the Iowa DOT considered appropriate to correct different distress types and severities. The Iowa DOT provided unit costs for each of the localized preventive maintenance actions included in these policies, and these costs are detailed in Appendix E. Please note that this information is of a general nature for the entire state. The maintenance policies and unit costs may require adjustment to reflect specific conditions at Spirit Lake Municipal Airport.

#### *Major Rehabilitation Unit Costs*

PAVER estimates the cost of major rehabilitation based on the predicted PCI of the pavement section. The Iowa DOT provided the costs for major rehabilitation, and they are presented in Appendix E. If major rehabilitation is recommended in the 5-year program, further engineering investigation will be needed to identify the most appropriate rehabilitation action and to more accurately estimate the cost of such work.

#### *Budget and Inflation Rate*

An unlimited budget with a start date of July 1, 2019, and an inflation rate of 1.5 percent was used during the analysis.

### Analysis Approach

The 5-year M&R program was prepared with the goal of maintaining the pavements above established critical PCIs. During this analysis, major rehabilitation was recommended for pavements in the year they dropped below their critical PCI. For the first year (2019) of the analysis only, a localized preventive maintenance plan was developed for those pavement sections that were above their critical PCI. If major rehabilitation was triggered for a section in 2020 or 2021, then localized maintenance was not recommended for 2019. While localized preventive maintenance should be an annual undertaking at Spirit Lake Municipal Airport, it is not possible to accurately predict the propagation of cracking and other distress types. Therefore, the airport should budget for maintenance every year and can use the 2019 localized preventive maintenance plan as a baseline for that work. As the pavements age, it can be assumed that the amount of localized preventive maintenance required will increase.

## Analysis Results

A summary of the M&R program for Spirit Lake Municipal Airport is presented in Table 2. Detailed information on the recommended localized preventive maintenance plan for 2019 is contained in Appendix F.

Table 2. 5-year M&R program under an unlimited funding analysis scenario.

| Year | Branch <sup>1</sup> | Section <sup>1</sup> | Surface Type <sup>2</sup> | Type of Repair <sup>3</sup> | Estimated Cost <sup>4</sup> |
|------|---------------------|----------------------|---------------------------|-----------------------------|-----------------------------|
| 2019 | A015I               | 01                   | AAC                       | Major Rehabilitation        | \$169,944                   |
| 2019 | R165I               | 01                   | AAC                       | Major Rehabilitation        | \$1,490,618                 |
| 2019 | T015I               | 01                   | AAC                       | Major Rehabilitation        | \$40,658                    |

**Total Estimated Cost: \$1,702,000**

<sup>1</sup>See Figure 3 for the location of the branch and section.

<sup>2</sup>AC = asphalt cement concrete; AAC = asphalt overlay on AC; PCC = portland cement concrete; APC = asphalt overlay on PCC.

<sup>3</sup>Major Rehabilitation: such as pavement reconstruction or an overlay. Localized Preventive Maintenance: such as crack sealing or patching.

<sup>4</sup>The costs provided are of a general nature for the entire state and may require adjustment to reflect specific conditions at the airport.

The recommendations made in this report are based on a broad network-level analysis and meant to provide Spirit Lake Municipal Airport with an indication of the type of pavement-related work required during the next 5 years. Further engineering investigation may be necessary to identify which repair action is most appropriate. In addition, the cost estimates provided are based on overall unit costs for the entire state, and Spirit Lake Municipal Airport should adjust the plan to reflect local costs.

Because an unlimited budget was used in the analysis, it is possible that the pavement repair program may need to be adjusted to consider economic and/or operational constraints. The identification of a project need does not necessarily mean that state or federal funding will be available in the year it is indicated. It is important to remember that regardless of the recommendations presented within this report, Spirit Lake Municipal Airport is responsible for repairing pavements where existing conditions pose a hazard to safe operations.

## General Maintenance Recommendations

In addition to the specific maintenance actions presented in Appendix F, it is recommended that the following strategies are considered for prolonging pavement life:

1. Regularly inspect all safety areas of the airport and document all inspection activity.
2. Conduct an aggressive campaign against weed growth through timely herbicide applications and mowing programs of the safety areas. Vegetation growth in pavement cracks is very destructive and significantly increases the rate of pavement deterioration.
3. Implement a periodic crack and joint sealing program. Keeping water and debris out of the pavement system by sealing cracks and joints is a proven and cost-effective method of extending the life of the pavement system.

4. Ensure that dirt does not build up along the edges of the pavements. This can create a “bathtub” effect, reducing the ability of water to drain away from the pavement system.
5. Closely monitor the movement of heavy equipment (particularly farming, construction, and fueling equipment) to make sure it is only operating on pavements that are designed to accommodate heavy loads. Failure to restrict heavy equipment to appropriate areas may result in the premature failure of airport pavements.



---

## SUMMARY

This report documents the results of the pavement evaluation conducted at Spirit Lake Municipal Airport. A visual inspection of the pavements in 2018 found that the overall condition of the pavement network is a PCI of 34. A 5-year pavement repair program, shown in Table 2, was generated for Spirit Lake Municipal Airport, which revealed that approximately \$1,702,000 needs to be expended on M&R. Spirit Lake Municipal Airport should utilize these study results to assist in planning for future maintenance needs as part of the airport CIP planning process.

## **APPENDIX A**

### **CAUSE OF DISTRESS TABLES**

Table A-1. Cause of pavement distress, asphalt-surfaced pavements.

| <b>Distress Type</b>      | <b>Probable Cause of Distress</b>  |
|---------------------------|--|
| Alligator Cracking        | Fatigue failure of the asphalt surface under repeated traffic loading.   |
| Bleeding                  | Excessive amounts of asphalt cement or tars in the mix or low air void content, or both.   |
| Block Cracking            | Shrinkage of the asphalt and daily temperature cycling; it is not load associated.   |
| Corrugation               | Traffic action combined with an unstable pavement layer.   |
| Depression                | Settlement of the foundation soil or can be “built up” during construction.  |
| Jet-Blast Erosion         | Bituminous binder has been burned or carbonized.   |
| Joint Reflection Cracking | Movement of the concrete slab beneath the asphalt surface due to thermal and moisture changes.   |
| L&T Cracking              | Cracks may be caused by (1) a poorly constructed paving lane joint, (2) shrinkage of the asphalt surface due to low temperatures or hardening of the asphalt, or (3) reflective cracking caused by cracks in an underlying PCC slab. |
| Oil Spillage              | Deterioration or softening of the pavement surface caused by the spilling of oil, fuel, or other solvents.   |
| Patching                  | N/A  |
| Polished Aggregate        | Repeated traffic applications.   |
| Raveling                  | Asphalt binder may have hardened significantly, causing coarse aggregate pieces to dislodge.   |
| Rutting                   | Usually caused by consolidation or lateral movement of the materials due to traffic loads.   |
| Shoving                   | Where PCC pavements adjoin flexible pavements, PCC “growth” may shove the asphalt pavement.  |
| Slippage Cracking         | Low strength surface mix or poor bond between the surface and the next layer of the pavement structure.  |
| Swelling                  | Usually caused by frost action or by swelling soil.  |
| Weathering                | Asphalt binder and/or fine aggregate may wear away as the pavement ages and hardens.   |

Table A-2. Cause of pavement distress, PCC pavements.

| <b>Distress Type</b>        | <b>Probable Cause of Distress</b>   |
|-----------------------------|---|
| ASR                         | Chemical reaction of alkalis in the portland cement with certain reactive silica minerals. ASR may be accelerated by the use of chemical pavement deicers.                    |
| Blowup                      | Incompressible materials in the joints.   |
| Corner Break                | Load repetition combined with loss of support and curling stresses.   |
| Durability Cracking         | Concrete's inability to withstand environmental factors such as freeze-thaw cycles.   |
| Joint Seal Damage           | Stripping of joint sealant, extrusion of joint sealant, weed growth, hardening of the filler (oxidation), loss of bond to the slab edges, or absence of sealant in the joint. |
| LTD Cracking                | Combination of load repetition, curling stresses, and shrinkage stresses.   |
| Patching (Small and Large)  | N/A   |
| Popouts                     | Freeze-thaw action in combination with expansive aggregates.  |
| Pumping                     | Poor drainage, poor joint sealant.  |
| Scaling                     | Over finishing of concrete, deicing salts, improper construction, freeze-thaw cycles, and poor aggregate.   |
| Settlement                  | Upheaval or consolidation.  |
| Shattered Slab              | Load repetition.  |
| Shrinkage Cracking          | Setting and curing of the concrete.   |
| Spalling (Joint and Corner) | Excessive stresses at the joint caused by infiltration of incompressible materials or traffic loads; weak concrete at the joint combined with traffic loads.                  |

## **APPENDIX B**

# **INSPECTION PHOTOGRAPHS**

A015I-01. Overview.



A015I-01. Alligator Cracking (Sample Unit No. 02).





A015I-01. Weathering (Sample Unit No. 03).



R165I-01. Overview.





R165I-01. Alligator Cracking (Sample Unit No. 25).



R165I-01. L&T Cracking (Sample Unit No. 02).





T015I-01. Overview.



T015I-01. Block Cracking (Sample Unit No. 02).



T025I-01. Overview.



## **APPENDIX C**

### **INSPECTION REPORT**

# Re-inspection Report

IA2018ALL

Report Generated Date: June 25, 2019

Network: 0F3 Name: SPIRIT LAKE MUNICIPAL AIRPORT

Branch: A015I Name: APRON 01 AT SPIRIT LAKE Use: APRON Area: 17,520.02SqFt

Section: 01 of 1 From: WEST END OF TWAY 01 To: SOUTH END OF APRON Last Const.: 01/01/2011  
Surface: AAC Family: IowaAACAPNorthern Zone: Category: Rank: P  
Area: 17,520.00SqFt Length: 292.00Ft Width: 60.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 11/29/2018 Total Samples: 4 Surveyed: 3

Conditions: PCI : 28

Inspection Comments:

Sample Number: 02 Type: R Area: 4,700.00SqFt PCI = 11

Sample Comments:

|                                     |   |               |             |
|-------------------------------------|---|---------------|-------------|
| 41 ALLIGATOR CRACKING               | M | 2,900.00 SqFt | Comments:   |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 92.00 Ft      | Comments:LS |
| 57 WEATHERING                       | L | 4,700.00 SqFt | Comments:   |

Sample Number: 03 Type: R Area: 4,700.00SqFt PCI = 17

Sample Comments:

|                                     |   |               |             |
|-------------------------------------|---|---------------|-------------|
| 57 WEATHERING                       | M | 50.00 SqFt    | Comments:   |
| 41 ALLIGATOR CRACKING               | M | 1,580.00 SqFt | Comments:   |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 60.00 Ft      | Comments:LS |
| 57 WEATHERING                       | L | 4,650.00 SqFt | Comments:   |

Sample Number: 04 Type: R Area: 4,150.00SqFt PCI = 59

Sample Comments:

|                                     |   |               |             |
|-------------------------------------|---|---------------|-------------|
| 41 ALLIGATOR CRACKING               | M | 50.00 SqFt    | Comments:   |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 220.00 Ft     | Comments:LS |
| 57 WEATHERING                       | L | 4,150.00 SqFt | Comments:   |

# Re-inspection Report

IA2018ALL

Report Generated Date: June 25, 2019

Network: 0F3 Name: SPIRIT LAKE MUNICIPAL AIRPORT

Branch: R165I Name: RUNWAY 16/34 SPIRIT LAKE Use: RUNWAY Area: 153,672.00SqFt

Section: 01 of 1 From: SOUTH END OF RUNWAY To: NORTH END OF RUNWAY Last Const.: 01/01/2010  
Surface: AAC Family: IowaAACRWNC&NCW Zone: Category: Rank: P  
Area: 153,672.00SqFt Length: 3,015.00Ft Width: 50.00Ft  
Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 11/29/2018 Total Samples: 31 Surveyed: 7

Conditions: PCI: 32

Inspection Comments:

Sample Number: 002 Type: R Area: 5,000.00SqFt PCI = 28

Sample Comments:

|                                     |   |               |             |
|-------------------------------------|---|---------------|-------------|
| 41 ALLIGATOR CRACKING               | M | 350.00 SqFt   | Comments:   |
| 57 WEATHERING                       | L | 5,000.00 SqFt | Comments:   |
| 52 RAVELING                         | L | 500.00 SqFt   | Comments:   |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 84.00 Ft      | Comments:LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 150.00 Ft     | Comments:FS |

Sample Number: 007 Type: R Area: 5,000.00SqFt PCI = 20

Sample Comments:

|                                     |   |               |               |
|-------------------------------------|---|---------------|---------------|
| 41 ALLIGATOR CRACKING               | M | 840.00 SqFt   | Comments:     |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 115.00 Ft     | Comments:FS W |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 45.00 Ft      | Comments:LS   |
| 57 WEATHERING                       | L | 5,000.00 SqFt | Comments:     |
| 52 RAVELING                         | L | 500.00 SqFt   | Comments:     |

Sample Number: 014 Type: R Area: 5,000.00SqFt PCI = 30

Sample Comments:

|                                     |   |               |             |
|-------------------------------------|---|---------------|-------------|
| 41 ALLIGATOR CRACKING               | M | 300.00 SqFt   | Comments:   |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 110.00 Ft     | Comments:LS |
| 57 WEATHERING                       | L | 5,000.00 SqFt | Comments:   |
| 52 RAVELING                         | L | 500.00 SqFt   | Comments:   |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 140.00 Ft     | Comments:FS |

Sample Number: 017 Type: R Area: 5,000.00SqFt PCI = 25

Sample Comments:

|                                     |   |               |             |
|-------------------------------------|---|---------------|-------------|
| 41 ALLIGATOR CRACKING               | M | 500.00 SqFt   | Comments:   |
| 57 WEATHERING                       | L | 5,000.00 SqFt | Comments:   |
| 52 RAVELING                         | L | 700.00 SqFt   | Comments:   |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 192.00 Ft     | Comments:FS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 14.00 Ft      | Comments:LS |

Sample Number: 021 Type: R Area: 5,000.00SqFt PCI = 43

Sample Comments:

|                                     |   |               |             |
|-------------------------------------|---|---------------|-------------|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 100.00 Ft     | Comments:LS |
| 41 ALLIGATOR CRACKING               | M | 100.00 SqFt   | Comments:   |
| 57 WEATHERING                       | L | 5,000.00 SqFt | Comments:   |
| 52 RAVELING                         | L | 500.00 SqFt   | Comments:   |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 365.00 Ft     | Comments:FS |

Sample Number: 025 Type: R Area: 5,000.00SqFt PCI = 26

Sample Comments:

|                                     |   |             |                  |
|-------------------------------------|---|-------------|------------------|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 455.00 Ft   | Comments:FS 2NDY |
| 41 ALLIGATOR CRACKING               | M | 600.00 SqFt | Comments:        |

# Re-inspection Report

IA2018ALL

Report Generated Date: June 25, 2019

---

|               |   |          |      |           |
|---------------|---|----------|------|-----------|
| 57 WEATHERING | L | 5,000.00 | SqFt | Comments: |
| 52 RAVELING   | L | 500.00   | SqFt | Comments: |

---

Sample Number: 028      Type: R      Area: 5,000.00SqFt      PCI = 51

Sample Comments:

|                                     |   |          |      |                  |
|-------------------------------------|---|----------|------|------------------|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 405.00   | Ft   | Comments:FS 2NDY |
| 57 WEATHERING                       | L | 5,000.00 | SqFt | Comments:        |
| 52 RAVELING                         | L | 500.00   | SqFt | Comments:        |
| 41 ALLIGATOR CRACKING               | M | 50.00    | SqFt | Comments:        |



# Re-inspection Report

IA2018ALL

Report Generated Date: June 25, 2019

Network: 0F3 Name: SPIRIT LAKE MUNICIPAL AIRPORT

Branch: T0151 Name: TAXIWAY 01 AT SPIRIT LAKE Use: TAXIWAY Area: 8,858.00SqFt

Section: 01 of 1 From: RUNWAY END 34 To: WEST END OF TAXIWAY 01 Last Const.: 01/01/2011

Surface: AAC Family: IowaAACTWNC&NCW Zone: Category: Rank: P

Area: 8,858.00SqFt Length: 245.00Ft Width: 30.00Ft

Shoulder: Street Type: Grade: 0.00 Lanes: 0

Section Comments:

Last Insp. Date: 11/29/2018 Total Samples: 2 Surveyed: 2

Conditions: PCI: 56

Inspection Comments:

Sample Number: 01 Type: R Area: 4,358.00SqFt PCI = 69

Sample Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 380.00 Ft Comments:LS

57 WEATHERING L 4,358.00 SqFt Comments:

52 RAVELING L 200.00 SqFt Comments:

Sample Number: 02 Type: R Area: 4,500.00SqFt PCI = 45

Sample Comments:

43 BLOCK CRACKING L 300.00 SqFt Comments:LS 3X3

41 ALLIGATOR CRACKING M 50.00 SqFt Comments:

48 LONGITUDINAL/TRANSVERSE CRACKING L 135.00 Ft Comments:LS

48 LONGITUDINAL/TRANSVERSE CRACKING M 62.00 Ft Comments:FS

57 WEATHERING L 4,500.00 SqFt Comments:

52 RAVELING L 200.00 SqFt Comments:

# Re-inspection Report

IA2018ALL

Report Generated Date: June 25, 2019

---

Network: 0F3      Name: SPIRIT LAKE MUNICIPAL AIRPORT

---

Branch: T0251      Name: TAXIWAY 02 AT SPIRIT LAKE      Use: TAXIWAY      Area: 4,698.00SqFt

---

Section: 01      of 1      From: SEE MAP      To: SEE MAP      Last Const.: 01/01/2018  
Surface: AC      Family: IowaACTWNC      Zone:      Category:      Rank: P  
Area: 4,698.00SqFt      Length: 200.00Ft      Width: 25.00Ft  
Shoulder:      Street Type:      Grade: 0.00      Lanes: 0

Section Comments:

---

Last Insp. Date: 11/29/2018 Total Samples: 1      Surveyed: 1

Conditions: PCI : 100

Inspection Comments:

---

Sample Number: 01      Type: R      Area: 4,698.00SqFt      PCI = 100

Sample Comments:

<NO DISTRESSES>



## **APPENDIX D**

### **WORK HISTORY REPORT**

Date:07/01/2019

**Work History Report**

1 of 2

Pavement Database:IA2018All

**Network:** 0F3      **Branch:** A015I      (APRON 01 AT SPIRIT LAKE)      **Section:** 01      **Surface:** AAC  
**L.C.D.:** 01/01/2011   **Use:** APRON      **Rank:** P   **Length:** 292.00 Ft      **Width:** 60.00 Ft      **True Area:** 17,520.00 SqF

| Work Date  | Work Code | Work Description              | Cost | Thickness (in) | Major M&R | Comments   |
|------------|-----------|-------------------------------|------|----------------|-----------|------------|
| 10/25/2014 | CS-AC     | Crack Sealing - AC            | \$0  | 0.00           | False     | -          |
| 10/25/2014 | ST-SC     | Surface Treatment - Seal Coat | \$0  | 0.00           | False     | -          |
| 01/01/2011 | OL-AS     | Overlay - AC Structural       | \$0  | 0.00           | True      | OL in 2011 |
| 06/30/1992 | NC-AC     | New Construction - AC         | \$0  | 0.00           | True      | -          |

**Network:** 0F3      **Branch:** R165I      (RUNWAY 16/34 SPIRIT LAKE)      **Section:** 01      **Surface:** AAC  
**L.C.D.:** 01/01/2010   **Use:** RUNWAY      **Rank:** P   **Length:** 3,015.00 Ft      **Width:** 50.00 Ft      **True Area:** 153,672.00 SqF

| Work Date  | Work Code | Work Description              | Cost | Thickness (in) | Major M&R | Comments   |
|------------|-----------|-------------------------------|------|----------------|-----------|------------|
| 07/02/2013 | ST-SC     | Surface Treatment - Seal Coat | \$0  | 0.00           | False     | -          |
| 07/01/2013 | CS-AC     | Crack Sealing - AC            | \$0  | 0.00           | False     | -          |
| 01/01/2010 | OL-AS     | Overlay - AC Structural       | \$0  | 0.00           | True      | OL in 2010 |
| 06/30/1992 | NC-AC     | New Construction - AC         | \$0  | 0.00           | True      | -          |

**Network:** 0F3      **Branch:** T015I      (TAXIWAY 01 AT SPIRIT LAKE)      **Section:** 01      **Surface:** AAC  
**L.C.D.:** 01/01/2011   **Use:** TAXIWAY      **Rank:** P   **Length:** 245.00 Ft      **Width:** 30.00 Ft      **True Area:** 8,858.00 SqF

| Work Date  | Work Code | Work Description              | Cost | Thickness (in) | Major M&R | Comments   |
|------------|-----------|-------------------------------|------|----------------|-----------|------------|
| 10/25/2014 | ST-SC     | Surface Treatment - Seal Coat | \$0  | 0.00           | False     | -          |
| 10/25/2014 | CS-AC     | Crack Sealing - AC            | \$0  | 0.00           | False     | -          |
| 01/01/2011 | OL-AS     | Overlay - AC Structural       | \$0  | 0.00           | True      | OL in 2011 |
| 06/30/1992 | NC-AC     | New Construction - AC         | \$0  | 0.00           | True      | -          |

**Network:** 0F3      **Branch:** T025I      (TAXIWAY 02 AT SPIRIT LAKE)      **Section:** 01      **Surface:** AC  
**L.C.D.:** 01/01/2018   **Use:** TAXIWAY      **Rank:** P   **Length:** 200.00 Ft      **Width:** 25.00 Ft      **True Area:** 4,698.00 SqF

| Work Date  | Work Code | Work Description      | Cost | Thickness (in) | Major M&R | Comments   |
|------------|-----------|-----------------------|------|----------------|-----------|------------|
| 01/01/2018 | NC-AC     | New Construction - AC | \$0  | 0.00           | True      | FIELD EST. |

**Summary:**

| <b>Work Description</b>       | <b>Section Count</b> | <b>Area Total (SqFt)</b> | <b>Thickness Avg (in)</b> | <b>Thickness STD (in)</b> |
|-------------------------------|----------------------|--------------------------|---------------------------|---------------------------|
| Crack Sealing - AC            | 3                    | 180,050.00               | .00                       | .00                       |
| New Construction - AC         | 4                    | 184,748.00               | .00                       | .00                       |
| Overlay - AC Structural       | 3                    | 180,050.00               | .00                       | .00                       |
| Surface Treatment - Seal Coat | 3                    | 180,050.00               | .00                       | .00                       |

## **APPENDIX E**

### **LOCALIZED PREVENTIVE MAINTENANCE POLICIES AND UNIT COST TABLES**

Table E-1. Localized preventive maintenance policy, asphalt-surfaced pavements.

| <b>Distress Type</b>      | <b>Severity Level</b> | <b>Maintenance Action</b> |
|---------------------------|-----------------------|---------------------------|
| Alligator Cracking        | Low                   | Monitor                   |
| Alligator Cracking        | Medium                | Asphalt Patch             |
| Alligator Cracking        | High                  | Asphalt Patch             |
| Bleeding                  | N/A                   | Monitor                   |
| Block Cracking            | Low                   | Monitor                   |
| Block Cracking            | Medium                | Crack Seal—Asphalt        |
| Block Cracking            | High                  | Crack Seal—Asphalt        |
| Corrugation               | Low                   | Monitor                   |
| Corrugation               | Medium                | Asphalt Patch             |
| Corrugation               | High                  | Asphalt Patch             |
| Depression                | Low                   | Monitor                   |
| Depression                | Medium                | Monitor                   |
| Depression                | High                  | Asphalt Patch             |
| Jet-Blast Erosion         | N/A                   | Asphalt Patch             |
| Joint Reflection Cracking | Low                   | Monitor                   |
| Joint Reflection Cracking | Medium                | Crack Seal—Asphalt        |
| Joint Reflection Cracking | High                  | Crack Seal—Asphalt        |
| L&T Cracking              | Low                   | Monitor                   |
| L&T Cracking              | Medium                | Crack Seal—Asphalt        |
| L&T Cracking              | High                  | Crack Seal—Asphalt        |
| Oil Spillage              | N/A                   | Asphalt Patch             |
| Patching                  | Low                   | Monitor                   |
| Patching                  | Medium                | Asphalt Patch             |
| Patching                  | High                  | Asphalt Patch             |
| Polished Aggregate        | N/A                   | Monitor                   |
| Raveling                  | Low                   | Monitor                   |
| Raveling                  | Medium                | Asphalt Patch             |
| Raveling                  | High                  | Asphalt Patch             |
| Rutting                   | Low                   | Monitor                   |
| Rutting                   | Medium                | Monitor                   |
| Rutting                   | High                  | Asphalt Patch             |
| Shoving                   | Low                   | Monitor                   |
| Shoving                   | Medium                | Asphalt Patch             |
| Shoving                   | High                  | Asphalt Patch             |
| Slippage Cracking         | N/A                   | Asphalt Patch             |
| Swelling                  | Low                   | Monitor                   |
| Swelling                  | Medium                | Monitor                   |
| Swelling                  | High                  | Asphalt Patch             |
| Weathering                | Low                   | Monitor                   |
| Weathering                | Medium                | Monitor                   |
| Weathering                | High                  | Asphalt Patch             |

Table E-2. Localized preventive maintenance policy, PCC pavements.

| <b>Distress Type</b>        | <b>Severity Level</b> | <b>Maintenance Action</b> |
|-----------------------------|-----------------------|---------------------------|
| ASR                         | Low                   | Monitor                   |
| ASR                         | Medium                | Slab Replacement          |
| ASR                         | High                  | Slab Replacement          |
| Blowup                      | Low                   | Slab Replacement          |
| Blowup                      | Medium                | Slab Replacement          |
| Blowup                      | High                  | Slab Replacement          |
| Corner Break                | Low                   | Crack Seal—PCC            |
| Corner Break                | Medium                | Full Depth PCC Patch      |
| Corner Break                | High                  | Full Depth PCC Patch      |
| Durability Cracking         | Low                   | Monitor                   |
| Durability Cracking         | Medium                | Full Depth Patch          |
| Durability Cracking         | High                  | Slab Replacement          |
| Joint Seal Damage           | Low                   | Monitor                   |
| Joint Seal Damage           | Medium                | Joint Seal                |
| Joint Seal Damage           | High                  | Joint Seal                |
| LTD Cracking                | Low                   | Monitor                   |
| LTD Cracking                | Medium                | Crack Seal—PCC            |
| LTD Cracking                | High                  | Slab Replacement          |
| Patching (Small and Large)  | Low                   | Monitor                   |
| Patching (Small and Large)  | Medium                | Full Depth PCC Patch      |
| Patching (Small and Large)  | High                  | Full Depth PCC Patch      |
| Popouts                     | N/A                   | Monitor                   |
| Pumping                     | N/A                   | Monitor                   |
| Scaling                     | Low                   | Monitor                   |
| Scaling                     | Medium                | Partial Depth PCC Patch   |
| Scaling                     | High                  | Slab Replacement          |
| Settlement                  | Low                   | Monitor                   |
| Settlement                  | Medium                | Grinding                  |
| Settlement                  | High                  | Slab Replacement          |
| Shattered Slab              | Low                   | Crack Seal—PCC            |
| Shattered Slab              | Medium                | Slab Replacement          |
| Shattered Slab              | High                  | Slab Replacement          |
| Shrinkage Cracking          | N/A                   | Monitor                   |
| Spalling (Joint and Corner) | Low                   | Monitor                   |
| Spalling (Joint and Corner) | Medium                | Partial Depth PCC Patch   |
| Spalling (Joint and Corner) | High                  | Partial Depth PCC Patch   |

Table E-3. 2019 unit costs for preventive maintenance actions.

| Maintenance Action                      | Unit Cost  |
|---|------------|
| Asphalt Patch—Asphalt-Surfaced Pavement | \$13.66/sf |
| Crack Sealing—Asphalt-Surfaced Pavement | \$2.34/lf  |
| Partial Depth PCC Patch—PCC Pavement    | \$34.97/sf |
| Full Depth PCC Patch—PCC Pavement       | \$15.62/sf |
| Crack Sealing—PCC Pavement              | \$2.81/lf  |
| Joint Sealing—PCC Pavement              | \$2.81/lf  |
| Grinding—PCC Pavement                   | \$0.34/sf  |
| Slab Replacement—PCC Pavement           | \$15.62/sf |

Table E-4. 2019 unit costs (per square foot) based on pavement type and PCI ranges.

| Pavement Type | PCI Range 0-40 | PCI Range 40-50 | PCI Range 50-60 | PCI Range 60-70 | PCI Range 70-80 | PCI Range 80-90 | PCI Range 90-100 |
|---------------|----------------|-----------------|-----------------|-----------------|-----------------|-----------------|------------------|
| AC            | \$9.70         | \$4.59          | \$4.59          | \$4.59          | \$0.00          | \$0.00          | \$0.00           |
| PCC           | \$16.19        | \$7.65          | \$7.65          | \$7.65          | \$0.00          | \$0.00          | \$0.00           |

## **APPENDIX F**

# **YEAR 2019 LOCALIZED PREVENTIVE MAINTENANCE DETAILS**



Table F-1. Year 2019 localized preventive maintenance details.

No localized preventive maintenance is recommended for Spirit Lake Municipal Airport in 2019.



**PREPARED FOR**

Iowa Department of Transportation  
Aviation Bureau  
800 Lincoln Way  
Ames, Iowa 50010  
515-239-1691  
<https://iowadot.gov/aviation>

**AUGUST 2019**