

IOWA DEPARTMENT OF TRANSPORTATION

To Office Bridges and Structures Date February 1, 2014
Attention All Employees Ref No. 521.1
From Gary Novey
Office Bridges and Structures
Subject Correction of the English Rolled Steel Bridge Standards RS40-071-10, RS40-072-10, RS40-073-10, RS40-074-10, RS40-075-10, RS40-076-10, RS40-077-10, RS40-078-10, RS40-079-10, & RS40-080-10.
(CADD M0345)

Electronic copies are available in the following Office of Bridges and Structures standard directory **W:\Highway\Bridge\Standards\Bridges** and on the Internet:

<http://www.iowadot.gov/bridge/standard.htm>

The corrected standards are located on the Bridge Web site.

- The Rolled Steel Bridge Standards RS40-071-10, RS40-072-10, RS40-073-10, RS40-074-10, RS40-075-10, RS40-076-10, RS40-077-10, RS40-078-10, RS40-079-10, & RS40-080-10 were corrected to add a 4 inch Stud height to the current 3 1/2" and 5" Stud choices. This change occurs in the Note for stud heights found on these standard sheets.

For any questions, please check with Stuart Nielsen or Thayne Sorenson.

GAN/ssn