

IOWA DEPARTMENT OF TRANSPORTATION

To Office Bridges and Structures Date September 1, 2014
Attention All Employees Ref No. 521.1
From Gary Novey
Office Bridges and Structures
Subject Revision of the English H30-06 Bridges Standards listed below.
(CADD M0392)

Electronic copies are available in the following Office of Bridges and Structures standard directory **W:\Highway\Bridge\Standards\Bridges** and on the Internet:

<http://www.iowadot.gov/bridge/standard.htm>

This is the revision of the H30-06 Bridge Standards.

The H30-86-06 & H30-87-06 Bridge Standards were revised to extend the Macadam Stone area 2'-0 in front of the Bridge Wing.

The H30-88-06, H30-89-06, H30-90-06 & H30-91-06 Bridge Standards were revised to remove the TECHNICAL DATA INFORMATION – GEPTEXTILE FABRIC table shown on these standards. This information is in the Standard Specifications book (Article 4196.01,B, 6 – Table 4196.01-6) and does not need to be shown on these Standard Sheets. A note was added to these standard sheets referring to the Article. The surface flooding time was changed to 5 minute increments for the floodable backfill lifts.

For any questions, please check with Stuart Nielsen or Thayne Sorenson.

GAN/ssn