

IOWA DEPARTMENT OF TRANSPORTATION

To Office Bridges and Structures Date October 1, 2014
Attention All Employees Ref No. 521.1
From Gary Novey
Office Bridges and Structures
Subject Revision and corrections of the English Deck Rail Bridge Standards listed below.
(CADD M0398)

Electronic copies are available in the following Office of Bridges and Structures standard directory **W:\Highway\Bridge\Standards\Bridges** and on the Internet:

<http://www.iowadot.gov/bridge/standard.htm>

Standards 1028A and 1028SA were revised to raise the outlet of the Drain Slots to 2 inches above the Bridge Deck Surface instead of out-letting at the bridge deck surface.

Standards 1029A and 1029B were corrected in the TYPICAL SECTION details to rename the definition of the bridge surface. It was defined as the Roadway Surface and has been re-defined as the Bridge Deck Surface.

For any questions, please check with Stuart Nielsen.

GAN/ssn