

COURSE SUMMARY

Certification Courses

Courses, Fees, and Pre-Requisites

Course Title	Description	Fees		Pre-Requisites
		New	Re-cert.	
Aggregate Sampler	Certified Sampling Technician	60	60	None
Aggregate Technician	Certified Aggregate Technician	480	120	None
Erosion Control	Erosion Control Technician	300	120	None
HMA Sampler	Certified HMA Sampling Technician	60	60	None
HMA Level I	Certified HMA Technician	600	120	Aggregate Technician
HMA Level II	Gyratory Mix Designer	600	120	HMA Level I
PCC Level I	Certified Concrete Tester	300	120	None
PCC Level II	Certified PCC Technician	480	120	Aggregate Technician & PCC Level I
PCC Level III	PCC Mix Designer	480	120	Level II PCC
Prestress Technician	Prestress Technician	360	120	•PCC Level I or ACI Level I
Ride Quality	Ride Quality Technician	240	120	None
Soils Technician	Soils Technician	240	120	None
Nuclear Gauge	Nuclear Gauge Operator (DOT ONLY)	N/A	N/A	None

•If the Certified Prestress Technician will be running gradations, they will need to be Aggregate Technician certified.

COURSE SUMMARY

Non-Certification Courses

Courses, Fees, and Pre-Requisites

Course Title	Description	Fee		Pre-requisite
		New	Recert	
HMA Paving Field Inspection	HMA Paving Inspection	--	--	None
Structures Field Inspection	Structural Inspection	--	--	None
PCC Paving Field Inspection	PCC Paving Inspection	--	--	None
Grading Field Inspection	Grade Inspection	--	--	None
Contract Administration Introduction	Introduction to Contract Administration	120	N/A	None